State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-200

FILE IN TRIPLICATE	OIL CONSERVATION DIVISION	Kevised 5-27-2004
DISTRICT I	1220 South St. Francis Dr.	WELL API NO.
1625 N. French Dr. , Hobbs, NM 88240	Santa Fe, NM 8750585 OCD	30-025-12504
DISTRICT II	1,000	5. Indicate Type of Lease STATE X FEE
1301 W. Grand Ave, Artesia, NM 88210	DEC 0 4 2015	STATE X FEE 6. State Oil & Gas Lease No.
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	DEC 0 4 2013	o. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		Section 32
1. Type of Well:		8. Well No. 532
Oil Well Gas Well Other Temporarily Abandoned 2. Name of Operator		9. OGRID No. 157984
Occidental Permian Ltd.		7. OOKID NO. 137984
Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, T	X 79323	
4. Well Location		
Unit Letter G : 2310	Feet From The North Line and 1650	Feet From The East Line
Section 32	Township 18-S Range	88-E NMPM Lea County
	11. Elevation (Show whether DF, RKB, RT GR, etc.)	
	3638' GL	
Pit or Below-grade Tank Application	or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT		
PULL OR ALTER CASING		
OTHER: TA status extension requ	uest X OTHER:	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any		
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
	i	Condition of Annuards
		Condition of Approval: notify
Run MI test to gain extension on temporary abandoned status.		OCD Hobbs office 24 hours
prior e		or of running MIT Test & Chart
		or and and the chart
I hereby certify that the information above i constructed or		
plan		
70. 1		
SIGNATURE MUNCLE	or an (attached) alternational plan	
11227	or an (attached) alternation of an internation o	ive Associate DATE 12/02/2015
11227	or an (attached) alternation of an internation o	ive Associate DATE 12/02/2015
TYPE OR PRINT NAME Mendy A For State Use Only	or an (attached) alternation of an internation o	ive Associate DATE 12/02/2015
TYPE OR PRINT NAME Mendy A	or an (attached) alternation of an internation o	ive Associate DATE 12/02/2015

DEC 1 0 2015

NOPROD REPORTED - 77 MONTHS