Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

NMOCD Hobbs

FORM APPROVED OMB NO. 1004-0135 31, 2010

NMNM02127B

	Expires, July	-
5.	Lease Serial No.	
	A IR ER IR ECO LOTTO	

SUNDRYN	OTICES	AND KE	PORIS	ON WELLS	
Do not use this	form for	proposals	s to drill	or to re-enter an	
shandoned well	Hen for	m 3160-3/	APD) for	r such proposals	

6. If Indian, Allottee or Tribe Name

abandoned well. Use i	6			
SUBMIT IN TRIPLICATI	7. If Unit or CA/Agreement, Name and/or No 8910064550			
Type of Well Gas Well □ Other /	,		8. Well Name and No. LEA UNIT 02	
2. Name of Operator LEGACY RESERVES OPERATING L	Contact: CRAIG SPA PE-Mail: csparkman@legacylp.cc	ARKMAN om	9. API Well No. 30-025-02428-00-S1	/
3a. Address 303 W WALL SUITE 1600 Ph: MIDLAND, TX 79702		o. (include area code) 89-5200 Ext: 6334	Field and Pool, or Exploratory LEA	
4. Location of Well (Footage, Sec., T., R., M., o Sec 12 T20S R34E SENW 1980FNL 1		JAN 2 5 2016	11. County or Parish, and State LEA COUNTY, NM	

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION		ТҮРЕ О	F ACTION		
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
All Andrews Control of the Control o	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction	Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	▼ Temporarily Abandon		
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

LEGACY RESERVES OPERATING LP RESPECTFULLY REQUESTS TO TEMPORARILY ABANDON THE LEA UNIT #2 WHILE BEHIND PIPE INTERVALS ARE BEING IDENTIFIED AND EVALUATED. A CIBP WILL BE SET ABOVE ALL 3 PERFORATED INTERVALS.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that to	he foregoing is true and correct. Electronic Submission #316545 verifie For LEGACY RESERVES OPEL Committed to AFMSS for processing by JENN	RATING	NG LP, sent to the Hobbs
Name (Printed/Typed)	CRAIG SPARKMAN	Title	e OPERATIONS ENGINEER
Signature	(Electronic Submission)	Date	
	THIS SPACE FOR FEDERA	LUR	1111 1 0 0010
Approved By		Title	JAN 1 9 2010
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			fice BUREAU OF LANY MANUTURE CARLSBAD FIELD OFFICE

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

MUSS/000 1/25/2016

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 12 months ending 01/19/2017 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Lea Unit 02

- 1. Well is approved to be TA/SI for a period of 12 months or until 01/19/2017
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 01/19/2017
- 4. COA's met at this time.