Form 3160-5 (August 2007)

_Approved By____

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				3 or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				reement, Name and/or No.
1. Type of Well			8. Well Name and No EMSU 389).
☑ Oil Well ☐ Gas Well ☐ Otl		11.	2 5 2010	✓
Name of Operator XTO ENERGY INCORPORAT	IED .	EPHANIE RABADUE AN	9. API Well No. 30-025-04631-	00-S1 🗸
3a. Address 500 W ILLINOIS STREET SUITE 100 MIDLAND, TX 79701		b. Phone No. (include area code h: 432.620.6714	10. Field and Pool, or Exploratory EUNICE MONUMENT 11. County or Parish, and State LEA COUNTY, NM	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)	/ 58	S 11. County or Parish	, and State
Sec 14 T21S R36E SWNW 19	1	REC	5 2016	
12. CHECK APPE	ROPRIATE BOX(ES) TO I	NDICATE NATURE OF	OTICE, REPORT, OR OTHE	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	■ New Construction	Recomplete	Other
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	▼ Temporarily Abandon	
4.1.56.01	□ Convert to Injection	☐ Plug Back	■ Water Disposal	
Attach the Bond under which the wor following completion of the involved	ally or recomplete horizontally, given will be performed or provide the operations. If the operation results andonment Notices shall be filed of an inspection.) requests to TA the reference or 25sxs thru tbg. WOC 4 hours.	e subsurface locations and measurements. Bond No. on file with BLM/BI/Si in a multiple completion or recombly after all requirements, included well with the following process. Tag. SEE A	ured and true vertical depths of all perti . Required subsequent reports shall be completion in a new interval, a Form 310 ling reclamation, have been completed,	nent markers and zones. Filed within 30 days 50-4 shall be filed once and the operator has
14. I hereby certify that the foregoing is	Electronic Submission #323	228 verified by the BLM Wel	I Information System	,
Cor	For XTO ENERGY mmitted to AFMSS for proces	INCORPORATED, sent to sing by LINDA JIMENEZ on		
Name (Printed/Typed) STEPHANIE RABADUE		The second secon	ATORY ANALYST	
Signature (Electronic Submission)		Date 11/11/2	PPROVED	1/1

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

THIS SPACE FOR FEDERAL OR STATE OF FICE USE

Title

Office

MUB/OCD 1/25/2014

JAN 25 2016

2016

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 12 months ending 01/19/2017 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram
 with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

EMSU 389

- 1. Well is approved to be TA/SI for a period of 12 months or until 01/19/2017
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 01/19/2017
- 4. COA's met at this time.