State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103

FILE IN TRIPLICATE		S)		Revised 5-27-2004		
	UIL CONSERV	ATION DIVISION	WELL API NO.			
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	Hobbs 1220 South	MM 87505		25-37154		
DISTRICT II	30		5. Indicate Type of Lease			
1301 W. Grand Ave, Artesia, NM 88210	150/		STATE X	FEE		
DISTRICT III			6. State Oil & Gas Lease No	).		
1000 Rio Brazos Rd, Aztec, NM 87410						
SUNDRY NO	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agree	ement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA	NORTH HOBBS (G/SA) UNIT		
The state of the s	PPLICATION FOR PERMIT" (Form C-		Section 19	,		
Type of Well:			8. Well No. 616			
Oil Well X	Gas Well Other					
2. Name of Operator			9. OGRID No. 157984			
Occidental Permian Ltd.						
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)		
1017 W. Stanolind Rd., HOBBS,	NM 88240 505/3	97-8200	. <b></b>			
4. Well Location						
Unit Letter L : 1820	Feet From The SOUTH	_700	Feet From The WEST	Line		
S 10	Township 10.0		8-E NMPM	LEA County		
Section 19	Township 18-S  11. Elevation (Show whether DF, R.		8-E NMPM	LEA County		
	3661' GR	KB, KI OK, Ele.)				
Pit or Below-grade Tank Application	or Closure					
1						
Pit Type Depth of Ground				surface water		
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction	Material			
12 Ch1	L. A	Anna aCNI-Aira Danasa	Od D-4-			
Check Appropriate Box to Indicate Nature of Notice, Report, or NOTICE OF INTENTION TO:			SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERIN	NG CASING		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS DILIGA	ABANDONMENT		
		1				
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEM	IENT JOB			
OTHER:		OTHER:	New Well Completion	on X		
13. Describe Proposed or Completed Op	erations (Clearly state all pertinent d	etails and give nertinent da	ites including estimated date of	f starting any		
proposed work) SEE RULE 1103.						
• • •	•					
1. RUPU. Tst CIBP set @6600' to			•			
	4140-49, 4152-59, 4167-70, 4199		and 4254-77 using 2 spf 120	deg sp ph. (169 holes).		
	600 g 15% NEFE HCL acid in 44					
	5 jts 2-7/8" tbg w/drain valve. Inta	ike set @4087'.				
<ul><li>5. Install QCI wellhead connection.</li><li>6. RDPU. Clean Location.</li></ul>						
6. RDPU. Clean Location.						
Rig Up Date: 02/07/2006		•				
Rig Down Date: 02/09/2006						
I hereby certify that the information above is	true and complete to the best of my know	ledge and belief. I further cert	ify that any pit or below-grade tank	k has been/will be		
constructed or				_		
closed according to NMOCD guidelines	, a general permit	or an (attached) alterna	tive OCD-approved			
•		plan	L	J		
SIGNATURE	`	TITLE Workover Co	ompletion Specialist DA	TE 02/19/2006		

TITLE

E-mail address:

Robert Gilbert robert\_gilbert@oxy.com For State Use Only APPROVED BY TITLE

PETROLEUM ENGINEER

Workover Completion Specialist

505/397-8206 DATE

02/19/2006

DATE

TELEPHONE NO.

CONDITIONS OF APPROVAL IF ANY

TYPE OR PRINT NAME