Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103 October 13, 2009
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.
District II	OIL CONCEDUATION DIVISION		30-025-26535
1301 W. Grand Ave., Artesia, NM 88210 District III	rand Ave., Artesia, NM 88210  1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	zos Rd., Aztec, NM 87410 Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease No.
87505			7 7 7 77 77 77
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  PROPOSALS.)  1. Type of Well: Oil Well  Gas Well			7. Lease Name or Unit Agreement Name
			State L Gas Com
			8. Well Number 3
2. Name of Operator		==D 4 = 201C	9. OGRID Number 873
Apache Corp.	/	FEB 1 7 2016	
3. Address of Operator P O box Drawer D Monument NM	99265	OFWED	10. Pool name or Wildcat
	88203	RECEIVED	Eumont Yates 7RQ
4. Well Location			
Unit LetterE:1980feet from theN line and960feet from the			
Wline			
Section 20 Township 19S Range 37E NMPM Lea County			
11. Elévation (Show whether DR, RKB, RT, GR, etc.)			
12 Check A	nnronriate Roy to Indi	cate Nature of Notice	Report or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON ☑ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐			
PULL OR ALTER CASING	MULTIPLE COMPL	☐ CASING/CEMEN	IT JOB $\square$
DOWNHOLE COMMINGLE			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
O H 3315' - 3630'			
Plan to move in PU & POOH with tbg. RIH with CIBP & set @ +- 3265' & dump 35' of cement on top of the plug. Load the casing with			
packer fluid & pressure test to 500 psi & chart the results.			
Condition of App. notify  OCD Hobbs office 24 hours  Condition of App. notify  OCD Hobbs office 24 hours			
Condition of App. notify			
OCD Hobbs office 24 hours			
MAN THOUS OTHER 24 h Jurs			
nrior of running MIT Test & Chart			
Spud Date:	Rig Rel	ease Date:	
			The state of the s
I hereby certify that the information a	bove is true and complete t	to the best of my knowledg	ge and belief.
0 > 0			
SIGNATURE TITLE Instrument Tech DATE 2/16/2016			
SIGNATURE TITLE Instrument Tech DATE 2/16/2016			
Type or print nameJim Ellison E-mail address: _JD.Ellison@apacheccorp.com_ PHONE: _575-441-7734			
For State Use Only			
APPROVED BY: Marky STOCOWATTILE DIST SURRIVINOU DATE 2/22/2016			
Conditions of Approval (if any)!  FEB 2 3 2016			
			1 FD 7 2 7010 A