Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135

Expires: July 31, 2010

Lease Serial No. NMLC029405B

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. Ry By Fed. 12 V Multiple-See Attached			
2. Name of Operator Contact: RHONDA ROGERS CONOCOPHILLIPS COMPANY ✓ E-Mail: rogerrs@conocophillips.com					9. API Well No. 30-025-41008, Multiple-See Attached			
3a. Address	(include area code) 10. Field and Pool, or Exploratory MALJAMAR			y				
MIDLAND, TX 79710			WAR 02 2016		IVIALOAIVIAIX			
4. Location of Well (Footage, Sec., T.	Matter		11. County or Parish, and State					
MultipleSee Attached RECEIVED					LEA COUNTY, NM			
12. CHECK APPR	OPRIATE BOX(ES) TO	O INDICATE	NATURE OF 1	NOTICE, RI	EPORT, OR OTHER	R DATA		
TYPE OF SUBMISSION	SUBMISSION TYPE OF ACTION							
Notice of Intent	☐ Acidize	☐ Dee	□ Deepen		☐ Production (Start/Resume)		■ Water Shut-Off	
	☐ Alter Casing	☐ Frac	ture Treat	☐ Reclam	☐ Reclamation		l Integrity	
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomplete		Othe	er	
☐ Final Abandonment Notice	☐ Change Plans		_		rarily Abandon			
	☐ Convert to Injection	☐ Plug	☐ Plug Back		☐ Water Disposal			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) ConocoPhillips Company would like to remove RBP & DHC per DHC-4684-0. Attached is a current/proposed wellbore schematic, procedure and 2014 field study. NM OIL CONSERVATION ARTESIA DISTRICT JAN 2 5 2016 RECEIVED 14. Thereby certify that the foregoing is true and correct.								
Electronic Submission #321585 verified by the BLM Well Information System For CONOCOPHILLIPS COMPANY, sent to the Hobbs Committed to AFMSS for processing by JENNIFER SANCHEZ on 11/17/2015 (16JAS0138SE)								
Name (Printed/Typed) RHONDA ROGERS			Title STAFF REGULATORY TECHNICIAN					
Signature (Electronic S	Date 10/27/2015							
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE			
Approved By EDWARD FERNANDEZ			TitlePETROLEUM ENGINEER		Da	ate 01/22/2016		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Hobbs		Ka	5	1	
Title 18 U.S.C. Section 1001 and Title 43 U.S. States any false, fictitious or fraudulent s					ake to any department or a	agency of	the United	

Additional data for EC transaction #321585 that would not fit on the form

Wells/Facilities, continued

Agreement NMLC029405B NMLC029405B


Lease NMLC029405B NMLC029405B Well/Fac Name, Number RUBY FEDERAL 12 RUBY FEDERAL 12 **API Number** 30-025-41008-00-S1 30-025-41008-00-S2

Location Sec 18 T17S R32E NESW 1330FSL 1705FWL Sec 18 T17S R32E NESW 1330FSL 1705FWL

ConocoPhillips

CURRENT SCHEMATIC

RUBY FEDERAL 12



Ruby Federal 012 API #30-025-41008 DHC-4684-0 Yeso, GB/SA

Project Scope

Justification and Background: Recompletion


This well was fracked in the yeso then the SA10, then Grayburg San Andreas 7 &9 & the final step is to comingle all the zones.

Well Service Procedure:

- 1) Verify anchors have been tested before RU
- 2) MI review JSA prior to RU
- 3) Nipple down well head
- 4) TOOH with rods and pump. Visually inspect rods COOH for pitting and wear, change out as needed
- 5) Nipple up BOP, & pull out of hole with tubing and stand tubing.
- 6) Pick up and run in hole with
 - a. 4-3/4" Bit
 - b. (6) 28lb/ft drill collars
 - c. 2-7/8" 6.5 lb/ft J-55 production tubing (casing size: 5-1/2, 17#)
 - d. To composite bridge plug at 5340 ft. drill out plug with 10 ppg brine
- 7) 10ppg column of brine above the CBP and our weight of string should be more than enough to drill out plug safely
- 8) Continue running in the hole with bit and collars to PBD 6863'. Drill out any restrictions as necessary
- 9) Circulate on bottom until we get clean returns to surface
- 10) Once complete pull out of hole with bit, collars and tubing.
- 11) Run in hole with 173 joints of 2-7/8" 6.5# J-55 production tubing, set tubing anchor at 3402 ft (above all perfs), set seating nipple at 5159 ft.
- 12) While running in hole test the tubing to 5000 psi below the slips.
- 13) Nipple down the BOP & RIH with rods and pump
- 14) Nipple up the well head
- 15) Surface equip the well with existing BPU and operate at 7.8 SPM & 170" stroke (no change)
- 16) Space out pump; hang well on, test pump action.

Ruby Federal 012 API #30-025-41008 DHC-4684-0 Yeso, GB/SA

17) Place well on test



Conditions of Approval Ruby Federal 12 30-025-41008 ConocoPhillips January 22, 2016

- 1. Operator procedure approved as written.
- 2. Surface disturbance beyond the existing pad must have prior approval.
- 3. Closed loop system required.
- 4. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 5. <u>Subsequent sundry and Completion report with well test and wellbore schematic required.</u>
- 6. Work to be completed in 90 days.

EGF 012216