3000529146

Legacy Reserves

DAILY OPERATIONS REPORT - (All Days)

1/1/2016 thru 3/18/2016

Printed 3/18/2016 Page 1

ROCK QUEEN UNIT # 302	CHAVES Co., NM	BOLO ID: 300680.43.02
Zone: QUEEN Field: CAPROCK		
Fix communication/change out p	acker	
	(Day 1) e in rig up pulling unit. Trie e on edge of location is froze	
Daily Cost:\$1,450Cum. Cost:\$1,450		
a vacuum at 8bbls. Nipple de 1x packer and start pulling de and running over blow out pro- Fluid did not stop, began she followed the water before we blow out preventer shut in an not stab TIW valve due to tul joints 2 7/8" tubing. Tubing Loaded annulus with brine and	utting blow out preventer while were able to shut in tubing on nd noticed packer had set. CO2 bing being too light. Roustabe g was heavier allowing us to in d pumped another 80bbls down to ping 0.5bpm brine down annulus 3/8" IPC Seal Lube tubing.	w out preventer. Release AS- iced fluid coming up annulus e standing back stand. CO2 r blow out preventer. Had 2 blowing out of tubing, could out crew delivered two(2) nstal valve and secure well. ubing. Released packer and
Daily Cost: \$5,385 Cum. Cost: \$6,835		

Feb 19, 2016 Friday

(Day 3)

SIP- < 50#. Pump 100bbls brine down tubing, on vacuum. Pull out of hole with 20 joints 2 3/8" IPC Seal Lube Tubing. Pick up run in hole with 5 1/2" AS-1X nickle coated packer with a 1.50"F" seal nipple, 93 joints 2 3/8" IPC Seal Lube Tubing. EOT @ 3019'. Set packer, load and test 500#, good. Release on/off tool and pump 80bbls packer fluid down annulus. Latch back up to packer, top off packer fluid. Nipple down blow out preventer and nipple up well head. Test and chart annulus 560# for 30min with no loss of PSI. Notified production job is complete.

Rig down move out pulling unit.

Daily Cost: \$9,235 Cum. Cost: \$16,070

B& 3129/14