

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 354-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-26361 ✓
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name O.A. Woody ✓
8. Well Number 1 ✓
9. OGRID Number 300017 ✓
10. Pool name or Wildcat Knowles Devonian (36290)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Silver Spike Energy Operating of NM, LLC ✓

3. Address of Operator  
203 W Wall St, Ste 920, Midland, TX 79701

4. Well Location

Unit Letter E : 2310 feet from the North line and 330 feet from the West line  
Section 35 Township 16S Range 38E NMPM Lea County ✓

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3694 GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING/CEMENT JOB ☐

INT TO PA Am ✓  
P&A NR \_\_\_\_\_  
P&A R \_\_\_\_\_

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- MI Rig. NU BOP. Set Steel work pit (no earthen pit)
- PU work string open ended. Tag @ 3667'.
- RU pump truck circ. 10# gelled mud.
- TOH w/ W.S. to 1800' Spot 25 sx class 'C' cement plug.
- TOH w/ W.S. to 380'. Spot 25 sx class 'C' cement plug.
- TOH to surface. Spot 10 sx surface. Cut off wellhead. Install DH marker.
- Rig down. Cut off anchors. Clean location.

HOBBS OCD

MAY 09 2016

RECEIVED

Spud Date:

NOTIFY OCD 24 HOURS PRIOR TO BEGINNING  
PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 5/9/16

Type or print name M.Y. (Merch) Merchant E-mail address: mymerch@penrocoil.com PHONE: 575-492-1236

For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engr. Specialist DATE 05/11/2016

Conditions of Approval (if any):

MAY 11 2016



O.A. Woody #1 API #30-025-Z6361

From Hobbs 10.6 miles N on Hwy 132. Turn right  
Kar 0.3 mile

245

Surface.

25 SX.

Set New  
25 SX 1800'

Tagged @ 3667'  
w/ 2011

30 SX @ 3800'

13 3/8 - 48" @ 370 400 SX

25 SX @ 4500'

8 5/8, 32" @ 4805' 1200 SX

TOC Est per OGD 68800'

5 1/2"  
Tag @ 3750'

9/25/06

5 1/2" cut 18"

(990)

w/ 407  
p. 7.

Cone plugged it

CIBP @ 12,300

5 1/2", 17 & 20" @ 12408 w/ 1000 SX

12,408-12,428'

2011 Mayo Mans: 25 SX @ 4500

30 SX @ 3800' WOC. Tagged @ 3667'