Submit 1 Copy To Appropriate District Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 882 BBS EUC District II – (575) 748-1283	OIL CONSERVATION DIVISION 2 2016 1220 South St. Francis Dr.		Form C-103 /Revised July 18, 2013 WELL API NO. 30-025-31422		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 JUN 0 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NNRECEIVE 87505			 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. N/A 		
SUNDRY NOTICES AND R (DO NOT USE THIS FORM FOR PROPOSALS TO DRII DIFFERENT RESERVOIR. USE "APPLICATION FOR F PROPOSALS.)	REPORTS ON WELLS L OR TO DEEPEN OR PLUG BACK TO A		Name or Unit Agreement obbs (G/SA)	Name	
1. Type of Well: Oil Well Gas Well	Other Injection	8. Well N	Jumber 233		
2. Name of Operator Occidental Permian Ltd.		9. OGRI 1579	D Number		
3. Address of Operator		10. Pool	name or Wildcat		
P.O. Box 4294, Houston, TX 77210		Hobbs	(G/SA)		
4. Well Location					
Unit Letter G : 2245f	eet from the North line and	2420	feet from the East	line	
Section 4	Fownship 198 Range 38	NMPM	County Lea	/	
11. Elevat 3628'	ion (Show whether DR, RKB, RT, GR KB	etc.)			

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
	PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASIN	G 🗌
	TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.	P AND A	
	PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEMENT JOB		
	DOWNHOLE COMMINGLE						
	CLOSED-LOOP SYSTEM						
	OTHER:				OTHER:		

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

(4/25/2016) MIRU, ND flowline, ND WH, NU BOP, RU workfloor. Unseat 5 ½" injection pkr and POOH w/ injection pkr and 127 jts tbg. RU wireline and run wireline gauge ring and tag @4003'. RD WL and RIH w/ 4 ¾" bit, 123 jts workstring to 4130'. POOH w/ workstring and bit, RIH w/ WL, set 5 ½" CIBP @ 4070' and pressure test CIBP to 600 psi. Perf 5 ½" csg at 4016'-4034', 4026'-4044', total 88 holes. RIH w/ 2 jts tail pipe, 122 jts tbg, and 5 ½" treating packer; set tail pipe @ 4045' and pkr @3980'. Pressure test pkr to 600 psi and it held. Acidize perfs w/ 600 gals 15% acid and flush tbg w/ 30 BBLs FW, unseat treating pkr and POOH w/ pkr. RIH w/ 124 jts workstring, 5 ½" injection pkr, set injection pkr @ 3970' and pressure tested pkr to 600 psi which held. POOH w/ workstring and RIH w/ on/off tool, 124 jts tbg and 4' sub. Pressure tested tbg to 800 psi, pressure tested csg to 600 psi, both held. NDBOP, NU wellhead, popped pump out plug @ 2000 psi, pumped 50 BBLs 10 # BW @ 2 bpm @800 psi. Ran H-5 test. RD PU and equipment, cleaned location and MO location.

Spud Date:	4/25/2016	Rig Release Date:	5/2/2016	
I hereby certif	fy that the information above is true and c	complete to the best of	f my knowledge and belief.	
SIGNATURE	Land mitchall	TITLE Regulatory	Specialist	DATE 5/31 2016
Type or print For State Use APPROVED Conditions of	name Sarah Mitchell e Only BY: Makey Abour Approval (if any)	E-mail address: <u>sa</u> TITLE Dist	arah_mitchell@oxy.com	PHONE: 713-366-5469

