Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-05193 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE FEE 🗷 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A T. D. Pope DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well Other 9. OGRID Number 2. Name of Operator Stephens & Johnson Operating Co. 019958 3. Address of Operator 10. Pool name or Wildcat Denton Devonian P.O. Box 2249 Wichita Falls, Texas 76307-2249 4. Well Location 1980 660 feet from the North line and feet from the_ line Unit Letter **NMPM** County Township Range 35 14S 37E Lea Park 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3820' DF Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well _____ Distance from nearest surface water ___ Pit type _____ Depth to Groundwater __ Pit Liner Thickness: __ Below-Grade Tank: Volume ___ _bbls; Construction Material . 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. **PLUG AND TEMPORARILY ABANDON** \mathbf{x} **CHANGE PLANS ABANDONMENT PULL OR ALTER CASING MULTIPLE** CASING TEST AND **CEMENT JOB** COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

	Comment of the second
See Attachment	en e
hereby certify that the information above is true and complete to the best of my knowledge and belief grade tank has been will be constructed or closed according to NMOCD guidelines, a general permitor an (at SIGNATURE	tached) alternative OCD-approved plan
Type or print name Peyton S. Carnes, Jr.	Telephone No. (940) 723-8113
APPROVED BY Conditions of Approval, if any:	DATE APR 0 3 2006

- 1. Rum 7 3/4" bit and scrapper to liner @ 4635'. Pull bit and scrapper.
- 2. Run 4 1/2" bit and scrapper to 11900'. Load hole w/salt water.
- 3. Run packer and RBP to check for hole or holes in casing, and evaluate for squeeze repair. If hole or holes are below 9500', go to Step 4.
- 4. Set CIBP @ 11900' and dump 35' cement on plug. If hole is below 9500', set another CIBP and 35' cement @ 9500'.
- 5. Pressure up casing to 500 psig. If well passes test, file appropriate forms for formal TA.