

*** AMENDED PROCEDURE**

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised July 18, 2013

HOBBS OGD
 JUL 11 2016
 RECEIVED

WELL API NO. 30-025-27778
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name MGF - SUN
8. Well Number 1
9. OGRID Number 012361
10. Pool name or Wildcat House Yates Seven Rivers (Gas)

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Kaiser-Francis Oil Company

3. Address of Operator
P.O. Box 21468, Tulsa, OK 74121-1468

4. Well Location
 Unit Letter **N** : **660** feet from the **South** line and **1980** feet from the **West** line
 Section **32** Township **19S** Range **39E** NMPM **Lea** County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3579' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

*AMENDED NOTICE OF INTENTION TO:	SUBSEQUENT R
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
DOWNHOLE COMMINGLE <input type="checkbox"/>	
CLOSED-LOOP SYSTEM <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Kaiser-Francis Oil Company requests permission to plug and abandon the MGF-SUN #1 according to the following procedure:

- MIRU WOR.
- P/U CIBP and TIH w/tubing. Set CIBP @ 2970'. Spot 25 sxs Class "C" cmt on top of plug @ 2970'.
- Circ hole w/ approved 9.5# brine-based plugging mud w/ 25 sx gel/100 bbls. Test csg to 500#.
- Run CBL from above cement on CIBP to surface. Perf circulating holes @1750'. Establish circ w/annulus open.
- Pump cmt plug inside & outside 4 1/2" csg from 1750' to surf. w/450 sxs Class C cmt.
- Cut off wellhead and mark location w/ 4' marker as per NM requirements.
- Remediate location. WBD attached. *Verify cmt to surface*

Spud Date:

NOTIFY OCD 24 HOURS PRIOR TO BEGINNING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Teresa Mixon* TITLE Regulatory Compliance Analyst DATE 07/07/16
 Type or print name Teresa Mixon E-mail address: teresami@kfoc.net PHONE: 918-491-4591

APPROVED BY: *Mark White* TITLE Petroleum Engr. Specialist DATE 7/19/2016

Conditions of Approval (if any):

Previously approved 6/7/16 Amended to reflect changes in procedure.

WELLBORE DIAGRAM - 1/23/14

