

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-29423
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Jackson Unit
8. Well Number 2
9. OGRID Number 7377
10. Pool name or Wildcat Johnson Ranch Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐
2. Name of Operator EOG Resources, Inc.
3. Address of Operator PO Box 2267, Midland, TX 79702
4. Well Location Unit Letter O : 990 feet from the S line and 1980 feet from the E line Section 22 Township 24S Range 33E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3577

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ DOWNHOLE COMMINGLE ☐ OTHER: ☐	SUBSEQUENT REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING/CEMENT JOB ☐ OTHER: ☐	INT TO PA <u>Am</u> P&A NR _____ P&A R _____
---	---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 65
1. Spz 50 sx class H into perfs and displace to 12500'. WOC. Pressure up on plug.
 2. Circulate hole w/ mud laden fluid.
 3. Spot 25 sx class H @ 9000-8900. Spot 30 sx class H' at 9500' (spacer)
 4. Cut and POH 7" csg @ 5200'. Spot 30 sx class H' at 6500' (spacer)
 5. Spot 55 sx class C @ 5250-5050. WOC & Tag
 6. Spot 45 sx class C @ 1800-1700. WOC & Tag
 7. Spot 45 sx class C @ 850-750. WOC & Tag. Pressure test csg.
 8. Spot 35 sx class C @ 100-surface. Spot 45 sx class C' at 3100' (spacer)
 9. Cut off wellhead and weld on Dry Hole Marker. Spot 45 sx class C' at 1200' (T. Salt)
- Verify cement to surface all strings

Spud Date:

NOTIFY OCD 24 HOURS PRIOR TO BEGINNING PLUGGING OPERATIONS


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ben Montgomery TITLE Agent DATE 7-22-16
Type or print name Ben Montgomery E-mail address: benmc@bemandassociates.com PHONE: 732-580-7161
For State Use Only

APPROVED BY: Mark Whitaker TITLE Petroleum Engr. Specialist DATE 7/27/2016
Conditions of Approval (if any):

MB

API# 30-025-29423
Sect 00, T00S, R00E
1980' FSL & 660' FWL
LEA, NM


[illegible]

202 39. 1985817 deng -163. 5580444

Ref. 32.1985817
 Jorg-103.5580444

JACKSON UNIT #2

API# 30-025-29423
 Sect 00, T00S, R00E
 1988' FSL & 660' FWL
 LEA, NM



SPUD TD
 DRILLING
 LAST REVISED 6/22/2016 NC
 WI NRI

Formation Tops	GL	KB	Hole	AFE #
13-3/8" 48# H-40 STC Class C cmt	35' 11" @ 100-50' TAC	45' 54" @ 850-786 TAs	17-1/2"	
9-5/8" 36# K55/S80 STC Lite/Class C	45' 54" @ 1800-1200 Salt TAs	55' 54" @ 5250-5050 TAs	12-1/4"	
	5,100'	5,100'		
	TOC 6500' ts			
25' 54" @ 9000-8000 Base Springs		2-7/8" 6.5# N-80 w/seal assembly	8-3/4"	
522 50' @ 12500 to 12050 12500		TOL 12,565'		
7" 26# S95/P100 LTC Lite/Class H		12,912'	6-1/8"	
13,282' - 13,546'				
4-1/2" 15.1# S95/P110 FL45		13,707'		
WOLFCAMP				

ROD DETAIL			
COUNT	SIZE	ITEM	DEPTH
TUBING DETAIL			
COUNT	SIZE	ITEM	DEPTH

Tubular Dimensions	Collapse	Burst	ID	Drift	bbf/ft
					0
					0
					0
					0