

Submit 1 Copy To Appropriate District Office

HOBBS OCD

State of New Mexico Energy, Minerals and Natural Resources

Form C-103 Revised July 18, 2013

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

Aug 26 2016 RECEIVED

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-07481
5. Indicate Type of Lease STATE [X] FEE []
6. State Oil & Gas Lease No. 19552
7. Lease Name or Unit Agreement Name North Hobbs Unit (G/SA)
8. Well Number 131
9. OGRID Number 157984
10. Pool name or Wildcat Hobbs (G/SA)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3656' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [] Gas Well [] Other [] Injector []
2. Name of Operator Occidental Permian Ltd
3. Address of Operator P.O. Box 4294, Houston, TX 77210
4. Well Location Unit Letter L : 2310 feet from the South line and 330 feet from the West line
Section 30 Township 18S Range 38E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3656' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
CLOSED-LOOP SYSTEM []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [X] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
OTHER: Return to Injection []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU x NDWH x NUBOP. Checked pressure - tbg 0 PSI x csg 0 PSI. POOH 124 jts x on/off tool. Tbg was bad. RIH new on/off tool x new 126 jts good tbg. Checked pressure - tbg 1000 PSI x csg 600 PSI. Ran MIT and tested good. RD x NDBOP x NUWH x MO Location. Chart previously mailed to NMOCD
**** Well returned to Injection

Spud Date: 06/22/16 Rig Release Date: 06/24/16


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE April Hood TITLE Regulatory Coordinator DATE 08/24/2016

Type or print name April Hood E-mail address: April_Hood@Oxy.com PHONE: 713-366-5771

For State Use Only APPROVED BY: Mary Brown TITLE Dist Supervisor DATE 8/31/2016

RBDMS-mB



DATE
 BR 2222
 6/24/16

