

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Tony Delfin
Acting Cabinet Secretary

David Catanach, Director
Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

07-Sep-16

HOBBS OCD

SEP 07 2016

RECEIVED

MOREXCO INC
P. O. BOX 51208
MIDLAND TX 79710

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

				D-11-24S-37E	30-025-11094-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
09/07/2016	Routine/Periodic	Mark Whitaker	Yes	No	10/14/2016	iMAW1625139078	
Violations		Absent Well Identification Signs (Rule 103)					
Comments on Inspection:		Well sign not legible (Rule 19.15.16.8). NEED TO REPLACE WELL SIGN. 1ST NOTICE.					
				C-11-24S-37E	30-025-27489-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
09/07/2016	Routine/Periodic	Mark Whitaker	Yes	No	10/14/2016	iMAW1625139284	
Violations		Absent Well Identification Signs (Rule 103)					
Comments on Inspection:		Well sign not legible (Rule 19.15.16.8). NEED TO REPLACE WELL SIGN.					

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, 
Petroleum Engr. Specialist

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER
FIRST-CLASS MAIL
\$000.46⁵
09/07/2016 ZIP 88240
012E14642224

US POSTAGE

MOREXCO INC
PO BOX 51208
MIDLAND, TX 79710