Office Submit I Copy To Approp		State of New 1			Form C-103			
District I - (575) 393-616	-	Energy, Minerals and N	atural Resources	WELL ADINO	Revised July 18, 2013			
1625 N. French Dr., Hobb	os, NM 88240	WELL API NO. 30-025-26790						
District II – (575) 748-128 811 S. First St., Artesia, N	M 88210 HOBBS		5. Indicate Type of Lease					
District III - (505) 334-61	/8	1220 South St. F	rancis Dr.	STATE STATE STATE				
1000 Rio Brazos Rd., Azto <u>District IV</u> – (505) 476-34		2016 Santa Fe, NM	87505	6. State Oil & Gas Lea				
1220 S. St. Francis Dr., Sa 87505		and the state of the		La Carlon				
		ND REPORTS ON WEL		7. Lease Name or Unit Agreement Name				
		DRILL OR TO DEEPEN OR FOR PERMIT" (FORM C-101		CENTRAL VACUUM UNIT				
PROPOSALS.)				8. Well Number #146	/			
1. Type of Well: Oi		ell Other INJECTO	R					
2. Name of Operator		9. OGRID Number						
CHEVRON USA I 3. Address of Operation			/	4323	10. Pool name or Wildcat			
1616 W. BENDER		VACUUM; BLINEBRY						
4. Well Location				1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -				
Unit Letter_	G : 2465 1	feet from the <u>NORTH</u>	_line and <u>1335</u>	feet from the <u>EAST</u>	line			
Section	31 Tov	wnship 17S Ran	ge 35E NN	MPM County L	EA			
SE SEAL PROPERTY		Elevation (Show whether I	OR, RKB, RT, GR, et	(c.)				
HOW BEEN THE	3975	'GL						
1	Check Approp	oriate Box to Indicate	Nature of Notice	e, Report or Other Data	ı			
NOT	ICE OF INTENT	TION TO:	l cu	BSEQUENT REPOR	T OF:			
PERFORM REMEDIA		G AND ABANDON	REMEDIAL WO		ERING CASING			
TEMPORARILY ABA		RILLING OPNS. □ PAN						
PULL OR ALTER CA	The state of the s	NGE PLANS TIPLE COMPL	CASING/CEME					
DOWNHOLE COMM								
CLOSED-LOOP SYS								
OTHER:	4.00		OTHER:					
				and give pertinent dates, inc				
	y proposed work). SI apletion or recompletion		AC. For Multiple C	ompletions: Attach wellbo	re diagram of			
CHEVRON U	JSA INC HAS REPA	RED WELLL DUE TO	MIT FAILURE					
				VELL DOWN AND RIG U	P WIRE LINE AND			
		LLHEAD AND NIPPLE			DIGIT LID WORK			
				HOLE IN THE BOTTOM. ID PULL 1.43 PLUG, REL				
	E SWINGING @ 390		OF WIKE LINE AN	ND FULL 1.43 FLUG, KEL	EASE FACKER			
			ESS AND RUN BA	CK IN THE HOLE AND S	SET @ 3897', LAY			
DOWN WOR					, , , , , , , , , , , , , , , , , , , ,			
CONTIN	UED ON NEXT PAG	GE						
Spud Date:		Rig Release	Date:					
	m 11 - 15 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1							
I hereby certify that the	e information above is	s true and complete to the	best of my knowled	lge and belief.				
Λ	11							
CICNIATINE	by Honora-M	Junio -			1010111011			
SIGNATURE	My Druck VI	TITLE_	PERMITTING SPE	CIALIST DATE_	12/01//2016			
Type or print name C	INDY HERRERA-M	URILLO E-mail addres	s. Cherreramurillo	chevron com PHONE.	575-263-0431			
For State Use Quly	1 1				313-203-0431			
APPROVED BY: Maley ABrown TITLE DIST Superviol DATE 12/6/2016 Conditions of Approval (if any):								
APPROVED BY:	anus	TITLE	We Du	LEWGO DATE	46/2016			
Conditions of Approva	l (if any):							
RBDMS-CHARTV								

CVU #146 Wellbore Diagram

Created: Updated:	02/10/06 08/07/07	By: H	A. Irle LH	Well #: API	146	146 St. Lse: 857943 30-025-26790		
Updated: Lease: Field: Surf. Loc.: Bot. Loc.: County:	O4/18/11 By: PTB Central Vacuum Unit Vacuum (Grayburg-San Andres) 2,465' FSL & 1,335' FWL Lea St.: NM Active Injection Well			Unit Ltr.: TSHP/Rng: Unit Ltr.: TSHP/Rng: Directions:	G	Section: S-17 E-35 Section: Buckeye, NM	31 M	
Status:					CHEVNOFJ3020			
Surface Ca Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	13 3/8" 48# 357' 500 Yes Surface 17 1/2" The Casing 8 5/8" 24# 1,540' 1,200 Yes Surface 12 1/4"				4409, 28, 36, 57, 61, 64, 71 60, 66, 70, 74 2600 gls 15% 4511, acid 20 4511, pkr 429 balls, pkr 428 12/14/01 Stim test csg, replagls 15% NEFI 3/10/04 Tbg/F 1/06: Failed N 3/15/06 CTCC perfs 924 gls 3/07: test csg 1/08 MIT failu 10-23-08 Tag 9/12: Replace tbg w 4-1/2" / 10/11/16: Tut	2: Tag 4255, CO 47 ace well head, pkr 4 E, tag 4735, CO 47 Pkr Leak: Replace MIT 2: Tag 4278, CO 4 15%. 7: replace tbg, pkr 1 15%. 8: replace on-off ged @4387'. 8: wellhead. RIH w/AS1X pkr. set pkr a 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	42, 45, 48, 51, 54, 41, 44, 48, 51, pkr 4603, acid BP 4603, pkr 15 balls, RBP 15% NEFE 25 795, RBP 4214, 4190, acid 6000 795, pkr 4226. 1 joint. 792, acid wash tool overshot. 2-3/8" fiberlined at 3,900', holes in the 122nd	
4409, 28, 3 4532, 42, 4	0, 74, 77, 80, 95, 6, 45, 56, 64, 5, 48, 51, 54, 57, 61, 64, 71, 3, 35, 41, 44, 48, 51, 60, 66,				2-3/8" TK-15	Tbg		
4670, 74, 83		,,,,			Arrowset Pkr 1.43" Profile N	w/ on-off tool @ 3 Nipple	,899'	
					Perfs: 434	6' - 4683'		

PBTD: 4702' TD: 4,800

Procedure for Central Vacuum Unit #146

30-025-26790

10/14/2016 0 PSI on well, Move out 2 3/8' L-80 WS and MI 2 3/8" IPC Production tubing/ RIH with Production tubing to top of 4 ½" Packer @ 3899', Space out and circulate packer fluid, ND BOP and NU WH, test void to 5000 PSI, Burst pump out plug @ 2,200 PSI, Shut down.

10/15/2016 Check pressure 0 casing/0 tubing Perform MIT at 560 PSI held. Rig down.

Please see attached copy of wellbore diagram

