| BI | UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT UNDRY NOTICES AND REPORTS ON WELLS of use this form for proposals to drill or to re-enter an | | | | FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM40456 | | |
|---|---|------------|-------------------------------------|--|--|-----------------------|--|
| Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. | | | | | 6. If Indian, Allottee or Tribe Name | | |
| SUBMIT IN TRIPLICATE - Other instructions on reverse side. | | | | | 7. If Unit or CA/Agree | ment, Name and/or No. | |
| 1. Type of Well □ Gas Well □ Other | | | | | 8. Well Name and No. CHEVRON 12 FEDERAL 1 | | |
| 2. Name of Operator Contact: TAMMY R LINK MATADOR PRODUCTION COMPANYE-Mail: tlink@matadorresources.com | | | | | 9. API Well No. 30-025-29747 | | |
| 3a. Address 5400 LBJ FREEWAY, SUITE DALLAS, TX 75240 | 3b. Phone No. (include area code) Ph: 575-623-6601 Ext: 2465 | | | 10. Field and Pool, or Exploratory YOUNG; BONE SPRING NORTH | | | |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) | | | | | 11. County or Parish, a | | |
| Sec 12 T18S R32E Mer NMP NENW 330FNL 1980FWL | | | | | LEA COUNTY, NM | | |
| 12. CHECK APPI | ROPRIATE BOX(ES) TO |) INDICATE | ENATURE OF N | NOTICE, RI | EPORT, OR OTHER | R DATA | |
| TYPE OF SUBMISSION | | | | | | | |
| Notice of Intent | □ Acidize | Dee | Deepen | | Production (Start/Resume) 🔲 Water Shut-Off | | |
| Subsequent Report | Alter Casing | - | Fracture Treat | | ation | Well Integrity | |
| Final Abandonment Notice | | | New Construction Plug and Abandon | | plete Dther prarily Abandon | | |
| | Convert to Injection | | Plug Back | | Water Disposal | | |
| BLM Bond No. NMB0001079 Surety Bond No. RLB0015172 Amendment to prior report sent on 10/17/2016. * R/U WORKOVER RIG AND PULL RODS AND TUBING CURRENLTY IN HOLE. * DRILL OUT CEMENT RETAINER * RIH WITH WIRELINE, PERFORATE F/9,008'-9,014' (8 SHOTS TOTAL) * RIH WITH URELINE, PERFORATE F/9,008'-9,014' (8 SHOTS TOTAL) * RIH WITH 2-7/8" TUBING AND RETRIEVABLE PACKER SET @ 8,700' AND STIMULATE PERFORATIONS WITH 2,100 BBLS AND 135,000 LBS PROPPANT * RELEASE PACKER, POOH * RUN 2-3/8" TUBING AND RETIEVABLE PACKER SET @ 8,700' | | | | | | | |
| 14. I hereby certify that the foregoing is true and correct. Electronic Submission #355884 verified by the BLM Well Information System For MATADOR PRODUCTION COMPANY, sent to the Hobbs Committed to AFMSS for processing by DEBORAH MCKINNEY on 10/26/2016 () | | | | | | | |
| Name (Printed/Typed) TAMMY R LINK Title PRODUOTI | | | | | ALYST | | |
| Signature (Electronic S | Date 10/25/2 | 016 | (PPROVED | | | | |
| THIS SPACE FOR FEDERAL OR STATE OFFICE/USE | | | | | | | |
| Approved By | | | | | | ENT CAR | |
| Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. | | | | | | | |
| ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** | | | | | | | |

.

Additional data for EC transaction #355884 that would not fit on the form

32. Additional remarks, continued

T

* RUN RODS

. .

.....

1

SEE ATTACHED: CURRENT WELLBORE DIAGRAM AND PROPOSED WELLBORE DIAGRAM.





Chevron 12 Federal 1 30-025-29747 Matador Production December 07, 2016 Conditions of Approval

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

Work to be completed by March 07, 2017.

- 1. Must conduct a casing integrity test before <u>perforating and fracturing</u>. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails
- **2.** Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a **2000** (**2M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done. Operator to include well bore schematic of current well condition when work is complete.

JAM 120716