an in the second					O	CD-HOBBS		
UNITED STATES UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018			
SUNDRY	NOTICES AND REPORTS ON WELLS				5. Lease Serial No. NMNM77063			
Do not use this form for proposals to drill or to re-enter ap 0 6 2017 abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on parECEIVE					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well SQ Oil Well Gas Well Other					8. Well Name and No. CONTINENTAL APJ FEDERAL 3			
2. Name of Operator Contact: TINA HUERTA EOG Y RESOURCES, INC. E-Mail: tinah@yatespetroleum.com					9. API Well No. 30-025-36049			
3a. Address 3b. Phone No. (include area code) 105 SOUTH FOURTH STREET Ph: 575-748-4168 ARTESIA, NM 88210 Fx: 575-748-4585					10. Field and Pool or Exploratory Area DIAMONDTAIL; DELAWARE,SW			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State			
Sec 28 T23S R32E NWNW 660FNL 660FWL					LEA COUNTY, NM			
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICAT	E NATURE (OF NOTICI	E, REPORT, C	OR OTHER DATA	A	
TYPE OF SUBMISSION		TYPE OF ACTION						
□ Notice of Intent	□ Acidize	Deepen I		🗖 Produ	ction (Start/I	INT TO PA		
Subsequent Report	Alter Casing		aulic Fracturing	_		P&A NR	·	
	Casing Repair	_	 New Construction Plug and Abandon 		nplete	P&A R	M M	
Final Abandonment Notice	Change Plans							
Attach the Bond under which the w following completion of the involv testing has been completed. Final determined that the site is ready for 10/27-31/16 - RU unit. Unlo RIH and tagged at 5680 ft. tank. Rotated down to 5781 Attempted to latch onto tubi scale. RIH with same overs clean. Pumping 2 BPM at 6 not move. 11/1-3/16 - RIH with freepoi cut tubing. Circulated after to 6156 ft and circulated cle rotated and washed over tul tubing stub, pulled free. Ne	ed operations. If the operation re Abandonment Notices must be fi r final inspection. aded tubing and reverse u Drilled out at 5681 ft. Did r ft, would not go down any ng stub, could not. Bottom hot. Rigged up swivel, rota 00 psi, returns 1 bbl. Latcl nt tool to 6100 ft, showing f 4 hrs and turned loose. Ta an. End of shoe at 5500 ft bing to 6300 ft. Did not tag	sults in a multipled only after all r nit. Bled down not lose return more. Circula 4 ft of oversh ated and wash hed onto tubin free. RIH with togged at 5782 , RIH to 6156	completion or re equirements, inclu- n, reverse circu- s. Lost 15 bbls ted clean. Ble of looked like it down to 5782 g stub, pulled chemical cutte ft. Rotated an ft, rigged up s	completion in ding reclamation in the sin reverse d down. was in ft. Circulat 40 pts over, er to 6110 ft d washed d wivel and	a new interval, a ion, have been co ls. ed did , own	Form 3160-4 must be	filed once	
14. I hereby certify that the foregoing	d by the BLM Well Information System INC., sent to the Hobbs							
Name (Printed/Typed) TINA HUERTA			Title REG REPORTING SUPERVISOR					
Signature (Electronic Submission)			Date 11/29/2016					
	THIS SPACE F	OR FEDERA	L OR STAT	E OFFICE	USE			
				AC	CFPTFD	FOR REC	ORD	
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office			2017		
Title 18 U.S.C. Section 1001 and Title States any false, fictitious or fraudule	erson knowingly a within its jurisdiction	and willfully to on.	make to any dep	artment or agency of t	ne United			
(Instructions on page 2) ** OPERATOR-SUBMITTED ** OPERATOR-SUBMIT FOR RECORD ONLY MW/0CD 02/07/2017) ** OPER		ANDERADAGEM D FIELD OFFICE	ENT	
	/	11						

Additional data for EC transaction #359149 that would not fit on the form

32. Additional remarks, continued

11/4-9/16 - Tagged at 6318 ft. RU swivel, rotate down to 6905 ft. Latched onto tubing stub at 6905 ft. Attempt to release, TAC did not release. Pumped 45 bbls down casing 3 BPM at 800 psi. Returns 1/2 bbl. Tagged at 8670 ft. Cleaned out to 8707 ft. Spotted 30 sx Class H cement at 8700 ft. Displaced with 49 bbls. WOC. Tagged Bone Spring top at 8475 ft. Paul Flowers with Hobbs BLM

ft. Displaced with 49 bbls. WOC. Tagged Bone Spring top at 8475 ft. Paul Flowers with Hobbs BL witnessed tag. 11/10-14/16 - Set a 5-1/2 inch CIBP at 6912 ft. Broke circulation with 22 bbls, dropped 1.59 inch ball. Pumped 22 bbls, pressured up to 2500 psi. Tested casing to 600 psi in 5 min down to 200 psi. Attempted to balance hole - did not. Found bad casing from 5560 ft - 5823 ft. Dump 2 bailers with cement on top of CIBP at 6912 ft. Prepare to plug and abandon well. 11/15/16 - Tagged TOC at 6875 ft. Displaced hole with 200 bbls brine mud gel. 11/16/16 - Spotted 25 sx Class C cement at 6875 ft. WOC. Tagged TOC at 6660 ft. Paul Flowers with BLM witnessed tag. Pumped 200 sx Class C cement at 5823 ft, displaced to 5500 ft. 11/17/16 - Tagged TOC at 5437 ft. Tested squeeze to 300 psi, good. Paul Flowers with BLM witnessed tag Perforated at 4940 ft. Tested casing to 300 psi, good. Spotted 25 sx Class C cement from 4751 ft up to 1160 ft. Spotted 91 sx Class C cement from 931 ft up to surface. Topped off 5-1/2 inch casing with cement. 11/23/16 - Dug up cellar and cut off wellhead. Installed dry hole marker as per BLM and covered cellar. WELL IS PLUGGED AND ABANDONED.



Diagram last updated: 09/23/2016

B