

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-39067
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. BO-2287
7. Lease Name or Unit Agreement Name North Monument G/SA Unit 302708
8. Well Number 374
9. OGRID Number 873
10. Pool name or Wildcat Eunice Monument G/SA (23000)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐	
2. Name of Operator Apache Corp.	
3. Address of Operator P O box Drawer D Monument NM 88265	
4. Well Location Unit Letter _____ H _____: _____ 1330 _____ feet from the _____ N _____ line and _____ 1185 _____ feet from the _____ E _____ line Section _____ Township 19S Range 36E NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3658 GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

E-PERMITTING		SUBSEQUENT REPORT OF:	
F CONVERSATION _____ RBDMS _____		REMEDIAL WORK ☐	ALTERING CASING ☐
T RETURN TO _____ TA _____		COMMENCE DRILLING OPNS. ☐	P AND A ☐
F CSCG _____ ENVIRO _____ CHG LOC _____		CASING/CEMENT JOB ☐	
C INT TO PA _____ P&A NR _____ P&A R _____			
OTHER: ☐		OTHER: TA TEST ☒	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PERFS: 3686-4042

- 1.MIRU. POOH & LD RODS/TBG
- 2.SET CIBP @ 3656' DUMP BAIL 35' CMT ON TOP.
- 3.LOAD CSG W/ PKR FLUID
- 4.TEST CSG TO 550# FOR 30 MINUTES.
5. NOTIFY OCD 24 HRS BEFORE TA TESTING.
6. MEET OCD REP. GEORGE BOWER. PRESSURE UP ONCSG TO 560#. RECORD TEST ON CHART FOR 32 MIN. ENDING PRESSURE 560#. REQUEST TA STATUS FOR WELL. SEE ATTACHED CHART.

This Approval of Temporary
Abandonment Expires 2/2/2021

Spud Date:	Rig Release Date:
------------	-------------------

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joel Sisk TITLE SR. PUMPER DATE 2/3/17

Type or print name JOEL SISK E-mail address: joel.sisk@apacheccorp.com PHONE: 575-441-0793

For State Use Only

APPROVED BY: Mary Brown TITLE AO/II DATE 2/8/2017
Conditions of Approval (if any):

Graphic Controls

DATE 2/2/2017
BR 2222

Start

TP Status
Apache
nach monument G/SN
374

30-025-39067
A-25-195-34E
CA's Date 9/2/16
1000 ft depth
Ser # 500 #
Ser # 500 #
Sund 8/2/16
end 30

Mac/ky
Duffy

20 MIN.

0 MIN.

PRINTED IN U.S.A.

START →

Wind

end

Production Casing
5-1/2" 17# K-55 @ 4080' w/ 890 sxs to surface