

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
October 13, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-01139</b>
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>CrownQuest Operating, LLC</b>		6. State Oil & Gas Lease No. <b>B-9385</b>
3. Address of Operator <b>P.O. Box 53310, Midland, TX 79710</b>		7. Lease Name or Unit Agreement Name <b>New Mexico AN State</b>
4. Well Location Unit Letter <b>P</b> : <b>660</b> feet from the <b>South</b> line and <b>660</b> feet from the <b>East</b> line Section <b>22</b> Township <b>14S</b> Range <b>33E</b> NMPM County <b>Lea</b>		8. Well Number <b>4</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>4,201 GR</b>		9. OGRID Number <b>213190</b>
		10. Pool name or Wildcat <b>Saunders</b>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

Restoration Due By **02-16-2018**

INT TO PA  
P&A NR **PM, x**  
P&A R

BSEQUENT REPORT OF:

WORK ☐ ALTERING CASING ☐  
RILLING OPNS. ☐ P AND A ☒  
NT JOB ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02/03/17 MIRU plugging equipment. 02/06/17 Dug out cellar, ND well head, NU BOP. RIH w/ 2 3/8 tbg, tag'd out @ 6205'. Could not work tbg past 6205'. Pump'd 195 bbls MLF down 5 1/2 csg, pressure tested csg, held 0 psi. 02/07/17 POH. Set 5 1/2 packer @ 3983'. Pump'd 85 bbls H2O, pressure tst'd csg @ 3983-surface, held 700 psi. RIH w/ tbg, tag'd out @ 4080'. Worked tbg free, POH. 02/08/17 RIH w/ 4 3/4 bit & 5 1/2 csg scraper to 3180'. 02/09/17 Cleaned hole to 6000'. POH. RIH w/ packer, isolated holes in csg. Pump'd 25 bbls H2O @ 6200'. Spot'd 100 sx class C cmt @ 6200-5189' (Per Mark Whitaker w/ OCD's request). WOC. 02/10/17 No tag. Re-spot'd 60 sx cmt mixed w/ magma fiber @ 6200-5593'. WOC. No tag. Pump'd 20 bbls H2O w/ 3 sacks magma fiber. Spot'd 60 sx cmt @ 6200-5593'. WOC. 02/13/17 Tag'd plug @ 5990'. Pump'd 100 bbls MLF. Pressure tst'd csg, held 600 psi. Spot'd 25 sx cmt @ 4950-4697'. WOC. Tag'd plug @ 4695'. 02/14/17 Spot'd 25 sx cmt @ 4200-3947'. WOC. 02/15/17 Tag'd plug @ 3950'. Spot'd 25 sx cmt @ 2600-2347'. POH w/ tbg. Cut 5 1/2 csg @ 1640'. POH w/ 51 jts of 5 1/2 csg. Spot'd 45 sx cmt @ 1690-1486'. WOC. 02/16/17 Tag'd plug @ 1490'. Spot'd 45 sx cmt @ 413-239'. WOC. Tag'd plug @ 295'. Spot'd 30 sx cmt @ 100

Spud Date:

02/03/2017


Rig Release Date:

02/16/2017

(Continued next page)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE Lease Manager

DATE 03/15/2017

Type or print name Saul Leyva

E-mail address: sleyva@crowquest.com

PHONE: 432-559-9066

For State Use Only

APPROVED BY:



TITLE P.E.S.

DATE 03-27-2017

Conditions of Approval (if any):