

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-25578
5. Indicate Type of Lease STATE FEE <i>Fed</i>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		7. Lease Name or Unit Agreement Name Glenn Ryan -
2. Name of Operator BLM for Patterson Operating & Pumping Inc. DBA/Penergy /		8. Well Number 004 -
3. Address of Operator NMOCD 1625 North French Drive Hobbs, NM 88240		9. OGRID Number <i>188566</i> -
4. Well Location Unit Letter <u>O</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>11</u> Township <u>26S</u> Range <u>37E</u> NMPM Lea County		10. Pool name or Wildcat Leonard;Queen, South
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK F
 TEMPORARILY ABANDON C **INT TO PA**
 PULL OR ALTER CASING M **P&A NR**
 DOWNHOLE COMMINGLE **P&A R** *pm.x*

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A XX
 CASING/CEMENT JOB

OTHER: _____

OTHER: _____

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: *Mah Whitaba* TITLE *P.E.S.* DATE *03-29-2017*

Conditions of Approval (if any):

Plugging Report
Glenn Ryan #4
Lat: 32.0523167549 Lon: -103.131619205

3/16/2017 Cleared location and spotted rig on matting board. Dug out cellar and exposed 5 1/2" casing. Installed 5 1/2" larkin wellhead. Rigged up and installed BOP.

3/17/2017 Moved remaining equipment to location. Unloaded work string and stacked beside the rig on seals. Casing was standing full of fluid. Hooked up vac truck to casing. Picked up work string and tagged existing CIBP @ 2579'. SIOW.

3/20/2017 Circulated MLF and spotted 30 sx Class C cement on top of CIBP. WOC and tagged cement at 2279'. Tested casing to 500# and held. POOH to 1150' and spotted 25 sx Class C cement. POOH to 561' and circulated cement to surface. Took 60 sx. Rigged Down. Will cut off in the morning.

3/21/2017 Cut off wellhead. Filled up both strings to surface with 5 sx cement. Installed marker and cleared location.