

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-31258
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name YOUNG 16 STATE
8. Well Number 001
9. OGRID Number 162683
10. Pool name or Wildcat YOUNG; DELAWARE, N.

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
CIMAREX ENERGY CO. OF COLORADO

3. Address of Operator
600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701

4. Well Location
 Unit Letter: B ; 660 feet from the NORTH line and 1880 feet from the EAST line
 Section 16 Township 18S Range 32E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,798' - GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.
 Restoration Due By 04-25-2018

INT TO PA
 P&A NR INTX
 P&A R _____

SEQUENT REPORT OF:
 DR ALTERING CASING
 DRILLING OPNS. P AND A
 PLUG JOB

PLUGGED AND ABANDONED 04/26/17.

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 04/24/17: SET 5-1/2" CIBP @ 5,500'; CIRC. WELL W/ PXA FLUID; PRES. TEST 5-1/2" CIBP X CSG. TO 750# - HELD OK; PUMP 25 SXS. CMT. @ 5,500'-5,350'; PUMP 25 SXS. CMT. @ 4,485'; WOC.
- 04/25/17: TAG CMT. PLUG @ 4,253' (OK'D BY OCD); PUMP 25 SXS. CMT. @ 2,525'; WOC X TAG CMT. PLUG @ 2,350' (OK'D BY OCD); PUMP 40 SXS. CMT. @ 1,335'; WOC.
- 04/26/17: TAG CMT. PLUG @ 931'; MIX X CIRC. TO SURF. 60 SXS. CMT. @ 475'-3'; DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL GROUND LEVEL DRY HOLE MARKER.

MIRU: 04/22/17

RDMO: 04/26/17

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David A. Eyer TITLE: AGENT
 Type or print name: DAVID A. EYLER E-mail address: DEYLER@MILAGRO-RES.COM

DATE: 04/26/17
 PHONE: 432.687.3033

For State Use Only

APPROVED BY: Maheshwari TITLE P.E.S.
 Conditions of Approval (if any):

DATE 05/01/2017