

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources  
**HOBBS OCD**  
 OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-103  
 Revised July 18, 2013

MAY 03 2017  
**RECEIVED**

WELL API NO. 30-025-05401
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name HL Batton "A"
8. Well Number 1
9. OGRID Number 232611
10. Pool name or Wildcat Lovington Paddock
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3808' DF

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other TA

2. Name of Operator  
SUNDOWN ENERGY LP

3. Address of Operator  
16400 DALLAS PARKWAY, STE. 100 DALLAS, TX 75248

4. Well Location  
 Unit Letter E : 1653 feet from the North line and 330 feet from the West line  
 Section 5 Township 17S Range 37E LEA County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: TA'd well <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- MIRU PU. Conduct safety/objective meeting. Remove horsehead, configure/remove wellhead.
- POH w/rods & pump & tubing.
- RIH w/gauge ring to 6212'. POH & RIH w/ 5-1/2" CIBP. Set @ 6180'. Open perms 6215-6290'
- Load hole w/pkr fluid.
- Notified OCD 24 hrs prior to testing. Gary Robison, OCD, witnessed. Test date 4/26/17. Press test to 580 psi for 30 mins. End press 560 psi. Well TA'd. Chart attached.

This Approval of Temporary Abandonment Expires 4/26/2020 <sup>TM</sup>

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Belinda Bradley TITLE Admin. Asst. DATE 5/2/2017

Type or print name Belinda Bradley E-mail address: bbradley@sundownenergy.com PHONE 432-943-8770

APPROVED BY: Maley Brown TITLE AO/II DATE 5/4/2017


Conditions of Approval (if any):

RDMS - CHART - ✓

Graphic Controls

DATE 4-26-17  
BR 2221

Handwritten notes and data:  
H.C. Butler  
50-025-05401-00-00  
E 5-17s - 37c  
Cal date 3-3-17  
Ser # M+S # 1000#  
Start 550\*  
end 560\*  
Vary Robinson  
ZPC w/ M+S  
OCD



PRINTED IN U.S.A.