Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I – (575) 393-6161	State of New Mexico Form C-1 Oistrict I – (575) 393-6161 Energy, Minerals and Natural Resources WELL API NO. Oistrict II – (575) 748-1283 OHL CONSERNATION DIVISION 30-25-28905	
District II – (575) 748-1283	CONCEDIATION DIVIS	30-25-28905
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	CONSERVATION DIVIS	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe NM 87505	STATE A FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NEECEIVE 87505) Santa 1 c, 14141 67505	6. State Oil & Gas Lease No. 96101
87505 SLINDRY NOTICES AND	DEDODTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Kochia AAM State
1. Type of Well: Oil Well Gas Well Other SWD		8. Well Number 1 SWD
2. Name of Operator		9. OGRID Number
SUNDOWN ENERGY LP		232611
3. Address of Operator 16400 DALLAS PARKWAY, STE. 100 DALLAS, TX 75248		10. Pool name or Wildcat
4. Well Location	ALLAS, 1X /3248	Devonian
Unit Letter O: 990 feet from the SOUTH line and 2310 feet from the EAST line Section 35 Township 15S Range 36E NMPM LEA County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3855' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM		
OTHER: FAILED MIT - PLANS TO REPAIR		R: Did not convert to inj.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recompletion.		
MIRU PU. POH w/ tbg & p	okr. Test IPC tbg back in	n hole, replacing faulty tbg. Set pkr &
perform MIT.		
NOTIFY OCD 24 HOURS PRIOR		
	1	O RUNNING MIT TEST
Spud Date:	Rig Release Date:	
I hereby certify that the information above is tr	ue and complete to the best of my	knowledge and belief.
SIGNATURE DATE 08/18/2017		
0		
Type or print name Belinda Bradley E-mail address: bbradley@sundownenergy.com PHONE 432-943-8770		
For State Use Only		
	n 1	aver Engineer
APPROVED BY: Conditions of Approved (if any):	TITLEPetrol	eum Engineer DATE 08/22/17