	Office							
Submit [°] 1 Copy To Appropriate District (Jince	State of New	Mexico		F	Form C-103		
District I - (575) 393-6161	Energ	y, Minerals and N	Natural Resources	WELL ADI NO		ed July 18,2013		
<u>District II</u> - (575) 748-1283	1625 N. French Dr.,Hobbs, NM 88240					WELL API NO. 30-025-06126		
811 S. First St., Artesia, NM 88210	HOBDE OIL	CONSERVATI		5. Indicate Type	e of Lease			
Disrtict III - (505) 334-6178 1000 Rio Brazos Rd. Aztec, NM 87410	SEP 1.1 2017	1220 South St. H	Francis Dr.	STATE	7	FEE 🗆 🗸		
<u>District IV - (505)</u> 476-3460	7505 DECEIVE	Santa Fe, NM	1 87505	6. State Oil & C	Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87		A-3071						
	NOPICES AND REP	ORIS ON WELLS		7. Lease Name	or Unit Agreeme	ent Name		
(DO NOT USE THIS FORM FOR PROI RESERVIOR. USE "APPLICATION FO	Hans	en State (3066	501) /					
	8. Well Number	r	/					
1. Type of Well: Oil Well	Gas Well Other			9. OGRID Num	3			
2. Name of Operator	Apache Corpora	ation	1	9. OGKID Num	873	/		
3. Address of Operator	Apacite Corport			10. Pool Name				
	irpark Lane, Ste. 3	000, Midland, TX	79705	Eunice Mor	nument; Gray-	SA 23000		
4. Well Location								
Unit Letter Section	A : 660 16 Townshi	feet from the p 20S Ra	N line and nge 37E	990 feet f	from t E County	line		
Section		<i>p</i> 205 Ra (Show whether DR,	0	INMPIN	County	Lea		
		3563						
12	Check Appropriate	Box To Indicate N	Jature of Notice Rei	port or Other I	Data			
PERFORM REMEDIAL WORK	FINTENTION TO:		MEDIAL WORK					
TEMPORARILY ABANDON			MMENCE DRILLING		INT TO PA	Pmp		
PULL OR ALTER CASING			SING/CEMENT JOB		P&A NR			
DOWNHOLE COMMINGLE					P&A R			
CLOSED-LOOP SYSTEM								
OTHER:			HER:					
12 Describe proposed or cor	nalated anarations		artinant datails and	give portinent	datas includin	a astimated		
13. Describe proposed or condate of starting any proposed	* *	(Clearly state all p		- ·		0		
date of starting any proposed	work.) SEE RULE	(Clearly state all p		- ·		0		
	work.) SEE RULE	(Clearly state all p		- ·		0		
date of starting any proposed	work.) SEE RULE	(Clearly state all p		- ·		0		
date of starting any proposed	work.) SEE RULE	(Clearly state all p		- ·		0		
date of starting any proposed	work.) SEE RULE	(Clearly state all p		- ·		0		
date of starting any proposed proposed completion or recom Apache Corporation propos	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC	2. For Multiple Com	rocedure. A c	ch wellbore dia losed loop sys	agram or		
date of starting any proposed proposed completion or recom Apache Corporation propos	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC	2. For Multiple Com	rocedure. A c	ch wellbore dia losed loop sys	agram or		
date of starting any proposed proposed completion or recom Apache Corporation propos	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC	2. For Multiple Com	rocedure. A c	ch wellbore dia losed loop sys	agram or		
date of starting any proposed proposed completion or recom Apache Corporation propos	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC	2. For Multiple Com	rocedure. A c	ch wellbore dia losed loop sys	agram or		
date of starting any proposed proposed completion or recom Apache Corporation propos	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC	2. For Multiple Com	rocedure. A c	ch wellbore dia losed loop sys	agram or		
date of starting any proposed proposed completion or recom Apache Corporation propos	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC	2. For Multiple Com	rocedure. A cl D Rule 19.15.1	ch wellbore dia losed loop sys	agram or		
date of starting any proposed proposed completion or recom Apache Corporation propos	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed	2. For Multiple Com I by the attached pu I of required by OC	rocedure. A cl D Rule 19.15.1	ch wellbore dia losed loop sys	agram or		
date of starting any proposed proposed completion or recon Apache Corporation propos used for all flu	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed	2. For Multiple Com I by the attached pu I of required by OC	rocedure. A cl D Rule 19.15.1	ch wellbore dia losed loop sys	agram or		
date of starting any proposed proposed completion or recom Apache Corporation propos used for all flu Spud Date:	work.) SEE RULE npletion. ses to P&A the above ids from this wellb	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed NOTIFY OCD BEGINNING F	2. For Multiple Com I by the attached pu I of required by OC 24 HOURS PRIO PLUGGING OPER	rocedure. A cl D Rule 19.15.1 DR TO RATIONS	ch wellbore dia losed loop sys 7.14 NMAC.	agram or		
date of starting any proposed proposed completion or recon Apache Corporation propos used for all flu	work.) SEE RULE npletion. ses to P&A the above ids from this wellb	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed NOTIFY OCD BEGINNING F	2. For Multiple Com I by the attached pu I of required by OC 24 HOURS PRIO PLUGGING OPER	rocedure. A cl D Rule 19.15.1 DR TO RATIONS	ch wellbore dia losed loop sys 7.14 NMAC.	agram or		
date of starting any proposed proposed completion or record Apache Corporation propos used for all flue Spud Date:	work.) SEE RULE npletion. ses to P&A the above ids from this wellb	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed NOTIFY OCD BEGINNING F	2. For Multiple Com I by the attached po I of required by OC 24 HOURS PRIO PLUGGING OPER	rocedure. A cl D Rule 19.15.1 DR TO RATIONS	ch wellbore dia losed loop sys 7.14 NMAC.	agram or		
date of starting any proposed proposed completion or recom Apache Corporation propos used for all flu Spud Date:	work.) SEE RULE npletion. ses to P&A the above ids from this wellb	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed NOTIFY OCD BEGINNING F	2. For Multiple Com I by the attached pu I of required by OC 24 HOURS PRIO PLUGGING OPER	rocedure. A cl D Rule 19.15.1 DR TO RATIONS	ch wellbore dia losed loop sys 7.14 NMAC.	agram or		
date of starting any proposed proposed completion or record Apache Corporation propos used for all flu Spud Date:	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed NOTIFY OCD BEGINNING F and complete to th	2. For Multiple Com I by the attached po I of required by OC 24 HOURS PRIO PLUGGING OPER ne best of my knowle Sr. Reclamation Fo	rocedure. A cl D Rule 19.15.1 DR TO RATIONS edge and belief	ch wellbore dia	/7/17		
date of starting any proposed proposed completion or record Apache Corporation propos used for all flue Spud Date:	work.) SEE RULE npletion. ses to P&A the above ids from this wellb	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed NOTIFY OCD BEGINNING F and complete to th	2. For Multiple Com I by the attached po I of required by OC 24 HOURS PRIO PLUGGING OPER	rocedure. A cl D Rule 19.15.1 DR TO RATIONS edge and belief	ch wellbore dia	agram or		
date of starting any proposed proposed completion or record Apache Corporation propose used for all flue Spud Date:	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed NOTIFY OCD BEGINNING F and complete to th 	2. For Multiple Com I by the attached pu I of required by OC 24 HOURS PRIO PLUGGING OPER ne best of my knowle Sr. Reclamation Fo	rocedure. A cl D Rule 19.15.1 DR TO RATIONS edge and belief preman DAT corp.com PHC	ch wellbore dia losed loop sys 7.14 NMAC.	/7/17 556-9143		
date of starting any proposed proposed completion or record Apache Corporation propos used for all flue Spud Date:	work.) SEE RULE npletion.	(Clearly state all p 19.15.7.14 NMAC ve mentioned wel ore and disposed NOTIFY OCD BEGINNING F and complete to th 	2. For Multiple Com I by the attached po I of required by OC 24 HOURS PRIO PLUGGING OPER ne best of my knowle Sr. Reclamation Fo	rocedure. A cl D Rule 19.15.1 DR TO RATIONS edge and belief preman DAT corp.com PHC	ch wellbore dia losed loop sys 7.14 NMAC.	/7/17 556-9143		

	· · ·	LEASE NAME	
,		WELL # API #	
	Apache	COUNTY	LEA
	WELL BORE INFO.		
0	11" Hole 9 5/8" 36# @ 266' w/ 200 sx to surf		
794			
1587			λ
2381			
3174	2 3/8" tbg & pkr set @ 3658'		
	8 3/4" Hole 7" 24# @ 3700' w/ 800 sx to surf		6-7-17 Set CIBP @ 3660' w/ 35' cmt Grayburg perfs @ 3722' - 3917'
3968	CIBP @ 4000' w/ 35' cmt		
			Grayburg perfs @ 4018' - 4092'
4762			
	CIBP @ 5150' w/ 10 ⁴ cmt		Paddock perfs @ 5198' - 5238'
5555	RBP @ 5536'		Blinebry perfs @ 5617'-5746'
6349			Tubb perfs @ 6345' - 6560' \$Q
	CIBP @ 6620'		Drinkard perfs @ 6663' - 6840'
			х
7142	CIBP @ 6966'		Abo perfs @ 7042'-7052'
	CIBP @ 7680' w/ 35' cmt		Penn perfs @ 7758'-7780'
	8 3/4" Hole 4 1/2" 11.6# @ 7936'		CIBP @ 7815' Penn perfs @ 7848'-7865'
7936	w/ 730 sx to surf	PBTD @ 5150' TD @ 7986'	

5	Apache	LEASE NAME WELL # API # COUNTY	3 30-025-06126
	WELL BORE INFO.	000111	PROPOSED PROCEDURE
0	11" Hole 9 5/8" 36# @ 266' w/ 200 sx to surf		4. PUH & spot 25 sx Class "C" cmt from 316' to surf. (Surf Shoe & Water Board)
794			3. PUH & spot 25 sx Class "C" cmt from 1329' - 967'
1587			WOC/TAG (Top of Salt)
2381			2. PUH & spot 25 sx Class "C" cmt from 2440'-2078' WOC/TAG (Base of Salt)
3174	2 3/8" tbg & pkr set @ 3658'		1. MIRU P&A rig. RIH & verify CIBP @ 3660' CIRC w/MLF & spot 25 sx Class "C" cmt from 3625' - 3263' (perfs & Inter Shoe)
	8 3/4" Hole 7" 24# @ 3700' w/ 800 sx to surf		6-7-17 Set CIBP @ 3660' w/ 35' cmt Grayburg perfs @ 3722' - 3917'
3968	CIBP @ 4000' w/ 35' cmt		Grayburg perfs @ 4018' - 4092'
4762			
	CIBP @ 5150' w/ 10 cmt		Paddock perfs @ 5198' - 5238'
5555	RBP @ 5536'		Blinebry perfs @ 5617'-5746'
6349			Tubb perfs @ 6345' - 6560'
	CIBP @ 6620'		Drinkard perfs @ 6663' - 6840'
7142	CIBP @ 6966'		Abo perfs @ 7042'-7052'
7936	CIBP @ 7680' w/ 35' cmt 8 3/4" Hole 4 1/2" 11.6# @ 7936' w/ 730 sx to surf	PBTD @ 5150' TD @ 7986'	Penn perfs @ 7758'-7780' CIBP @ 7815' Penn perfs @ 7848'-7865'