

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*

5. Lease Serial No.  
NMLC030187

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
LA MUNYON 05 /

9. API Well No.  
30-025-10813-00-S1

10. Field and Pool or Exploratory Area  
LANGLIE

11. County or Parish, State  
LEA COUNTY, NM

**SUBMIT IN TRIPLICATE - Other instructions on page 2**

**HOBBS OCD**  
**SEP 11 2017**  
**RECEIVED**

1. Type of Well  
 Oil Well  Gas Well  Other

2. Name of Operator  
OXY USA INCORPORATED / Contact: DAVID STEWART  
E-Mail: david\_stewart@oxy.com

3a. Address  
P O BOX 4294  
HOUSTON, TX 77210-4294

3b. Phone No. (include area code)  
Ph: 432-685-5717  
Fx: 432-685-5742

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Sec 21 T23S R37E SWSW 660FSL 660FWL /  
32.284422 N Lat, 103.174263 W Lon

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

| TYPE OF SUBMISSION                                    | TYPE OF ACTION                                |  |   |  |
|---|---|--|---|--|
| <input type="checkbox"/> Notice of Intent             | <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen                      | <input type="checkbox"/> Production (Sta) |  |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Hydraulic Fracturing        | <input type="checkbox"/> Reclamation      |  |
| <input type="checkbox"/> Final Abandonment Notice     | <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction            | <input type="checkbox"/> Recomplete       |  |
|   | <input type="checkbox"/> Change Plans         | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily At   |  |
|   | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back                   | <input type="checkbox"/> Water Disposal   |  |

INT TO PA \_\_\_\_\_  
P&A NR \_\_\_\_\_  
P&A R PM X

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

6/27/2017 MIRU PU, dig out WH, check pressure, change valves.

6/28/2017 Check pressures - 15#-Tbg, 100#-5-1/2" csg, 10# - 8-5/8" csg, Bled off tbg & 8-5/8" csg. Pump BW down tbg to kill well, well did not load, on vacuum. RU BOP & adapter, pump BW, circ to surf, would die and come right back.

6/29/2017 Pump 14.5# mud several times to kill well, finally died. ND WH, NU BOP, tried to release TAC, tbg torqued up, stretch show tbg stuck @ 3022'.

6/30/2017 RIH w/ WL & tag @ 3440' and free point shows tbg to be 100% free @ 3410'. Called BLM-Steven Bailey rec appr to cut tbg @ 3400' & set CIBP @ 3368'. RIH w/ chemical cutter & cut tbg @ 3400', POOH w/ tbg. RIH w/ gauge ring & tag up @ 3400', POOH. RIH & set CIBP @ 3368', POOH.

**RECLAMATION**  
**DUE 1-7-18**

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #381382 verified by the BLM Well Information System**  
**For OXY USA INCORPORATED, sent to the Hobbs**  
**Committed to AFMSS for processing by PRISCILLA PEREZ on 07/19/2017 (16PP0948SE)**

Name (Printed/Typed) DAVID STEWART Title SR. REGULATORY ADVISOR

Signature (Electronic Submission) Date 07/14/2017

*Accepted for Record* THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By James C. Davis Title SPET Date 8-31-17

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office HO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**Additional data for EC transaction #381382 that would not fit on the form**

**32. Additional remarks, continued**

7/3/2017 RIH w/ tbg & tag CIBP @ 3368', circ hole w/ 10# MLF, M&P 25sx CL C cmt, calc TOC-3121', POOH. RIH & run CBL from 2800'-Surface, TOC on 1st stage @ 2375', 2nd stage @ 1170-744' w/ light cmt to 540'. RIH to 2722', M&P 25sx CL C cmt, PUH, WOC.

7/5/2017 RIH w/ tbg & tag cmt @ 2487', called BLM-Steven Bailey. PUH to 1217', M&P 25sx CL C cmt, PUH, WOC. RIH w/ pkr & isolated hole in 5-1/2" csg @ 544-576'. RIH & tag cmt @ 1009', called BLM-Steven Bailey discussed procedure. PUH to 640', M&P 25sx CL C cmt, PUH, WOC.

7/6/2017 RIH w/ tbg & tag cmt @ 498', pressure test csg to 500#, tested OK. Called BLM-Paul Swartz to update. PUH & set pkr @ 288', RIH & perf @ 358', EIR @ 3bpm @ 50# w/ full circulation. PUH w/ pkr & set @ 32', M&P 115sx CL C cmt, circ cmt thru 5-1/2" X 8-5/8", displace cmt to 100' in 5-1/2", SI-50#, WOC.

7/7/2017 RIH w/ tbg & tag cmt @ 104', POOH. Called BLM-Steve Bailey, approved tag. ND BOP, RIH w/ tbg to 104', M&P 15sx CL C cmt, circ cmt to surf, POOH w/ tbg & top w/ cmt. RDPU.