District I 1625 N. French E Phone: (575) 393 District II 811 S. First St., A Phone: (575) 748 District III 1000 Rio Brazos Phone: (505) 334 District IV 1220 S. St. Franc Phone: (505) 476	-6161 Fax: (575 artesia, NM 8821 -1283 Fax: (575) Road, Aztec, NN -6178 Fax: (505) is Dr., Santa Fe,	88240) 393-0720 0 748-9720 4 87410 334-6170 NM 87505 476-3462	HOP	3BS C	2017 -EN	nergy ED	State Minera Oil Con 1220 Sou Santa	of New I Is and N servation uth St. Fi a Fe, NM NTER, D	Mexico atural R 1 Divisio rancis D 87505	esou n r.	rces			Form C-101 Revised November 14, 2012	
APPLI	CATIO	N FO	R PEF	TIMS	TO DI	RILL,	RE-EN	TER, D	EEPEN	I, PL	UGBAC	K, Ol	R AD	D A ZONE	
ConocoPhillips Company P. O. Box 51810 Midland, TX 79710				and Address					² OGRID Number 217817 ³ API Number						
⁴ Property Code 31257 VACUUM			CUUM	³ Property Name GLORIETA EAST UNIT			lame IT	ie /			025-20882 * Well No. 003				
						^{7.} Sı	irface Lo	cation							
UL - Lot E	Section 27	Townshi 17S	ip 35E	Range		t Idn	Feet from 2310	NO	N/S Line RTH	330	Feet From	E/W WES	V Line T	County LEA	
UL - Lot E			ip .	Range		8. Proposed			N/S Line	Feet From		E/W	V Line	County	
						^{9.} Po	ol Inform	nation							
VACUUM;	Pool Name VACUUM; GB-SA					Name							Pool Code 62180		
RECOMPL	^{11.} Work Type ^{12.} Well Type RECOMPLETE/PB O					Additional Well Information			6	3945' KB			ound Level Elevation		
^{16.} Multiple ^{17.} Proposed Depth NO 6275' Depth to Ground water Distance f					^{18.} Formation VACUUM; GB-SA ace from nearest fresh water well				^{19.} Contractor Distance to near			^{20.} Spud Date 05/16/1964 arest surface water			
				21.	Propo	sed Ca	sing and	Cement P	rogram						
Туре				Casing Weight/ft			Setting Depth			Sacks of Cement			Estimated TOC		
SURF	12 1/4		9 5/8"		32#			1604'		0	ON RECORD		0	0	
PROD	ROD 7 7/8"		4 1/2"	11.6#		5#		6275'		0	ON RECORD		TC	TOC 3754'	
BP								6017'							
PLEASE SE	EE ATTA	CHED	PROCE					dditional ED WELI			MATIC &	ATTA	CHED	C-102	
				22.	Propos	sed Blo	wout Pr	evention P	rogram						
				Working Pressure			Test Pressure				Manufacturer				
^{23.} I hereby ce best of my kn I further cer 19.15.14.9 (B Signature: Printed name Title: Staff]	owledge and tify that I have NMAC Regulatory	l belief. ave com], if app Rogers 7 Techr	plied with licable.	19.15.14. Zers				Approved I Title: Approved I	By:	. CON		TION I	Per	ION troleum Enginee 99/13/19	
E-mail Addre	ss: rogerrs	@conc	cophilli	ips.com								1			
Date: 09/07	2017		DL	one: (432)		1.7.4		Conditions							

VACUUM GLORIETA EAST UNIT TRACT 26-003 API# 30-025-20882 PLUG BACK GLORIETA RECOMPLETE GB-SA

Justification and Background:

This project will recomplete the VGEU 26-03 to the San Andres formation and become part of the East Vacuum Grayburg San Andres Unit (EVGSAU). This well will be renamed the EVGSAU 2738-405.

Well Service Procedure:

- 1. Review JSA prior to RU on well.
- 2. MI RU Well Service Unit. ND wellhead. NU BOPE.
- 3. MI RU Wireline Services. NU 5000 PSI lubricator.
- 4. PU bailer, RIH and dump bail 5 sks Class C cement above CBP @ 6017.
- 5. PU CBP, RIH and set @ 4815' RIH and dump bail 5 sks Class C cement above CBP.
- PU & RIH w/guns to perforate first stage using 4" Titan Slick Gun w/ 7/8" super deep penetrating charges (or equivalent). Conduct any repeat gun runs as necessary to perforate as follows:

Interval Top	Interval Bottom	Interval Length	SPF	Phasing	Shot Count	
4368'	4377'	9'	3	120°	27	
4407'	4416'	9'	3	120°	27	
4423'	4443'	20'	3	120°	60	
4485'	4497'	12'	3	120°	36	
4563'	4574'	11'	3	120°	33	
4588'	4603'	15'	3	120°	45	

- 7. Pull fired guns into lubricator, bleed lubricator, & remove spent guns. Verify all shots fired. Record in WellView.
- 8. RDMO Wireline services once perfing is complete.
- 9. PU RBP and packer on tubing.
- 10. Hydro in hole to 5000 PSI.
 - RIH and set RBP @ 4675'

- Come up hole with packer and set @ 4463' (Note: Attempting to set packer between perfs from 4443' and 4485').
- 11. MIRU acidizing services. RU remote ball launcher.
- 12. Pump 110 bbls of 15% NEFE HCL, do not exceed 5000 psi surface pressure.
 - a. Pump 26 bbls of 15% NEFE HCL.
 - b. Pump 58 bbls of 15% NEFE HCL, dropping 57 ball sealers (7/8", 1.1 SG) evenly spaced.
 - c. Pump 26 bbls of 15% NEFE HCL.
 - d. Displace tubing and casing with 28 bbls fresh water.
- 13. Release packer and TIH to 4675' to retrieve RBP.
- 14. Come up hole and set RBP at 4463' (Note: Attempting to set RBP between perfs from 4443' and 4485').
- 15. Come up hole and set packer at 4330'.
- 16. Pump 150 bbls of 15% NEFE HCL, do not exceed 5000 psi surface pressure.
 - a. Pump 37 bbls of 15% NEFE HCL.
 - b. Pump 75 bbls of 15% NEFE HCL, dropping 147 ball sealers (7/8", 1.1 SG) evenly spaced.
 - c. Pump 37 bbls of 15% NEFE HCL.
 - d. Displace tubing and casing with 27 bbls fresh water.
- 17. Release packer and RIH to 4463' to retrieve RBP.
- 18. TOOH and laydown RBP and packer.
- 19. Hydro in hole with production tubing.
 - a. Set tubing anchor at 4300'.
 - b. Land end of tubing at 4660'.
- 20. TIH with 2" Insert pump and rods. Land pump, Load and test. Space pump. Hang well on.
- 21. RD. Clean up location.

