

HOBBS OCD

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

OCT 3 2017

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> <u>SALT WATER DISPOSAL</u>	WELL API NO. <u>30-025-20980</u>
2. Name of Operator <u>Buckeye LLC</u>	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator <u>PO Box 2724 Lubbock TX 79408</u>	6. State Oil & Gas Lease No. <u>E7723</u>
4. Well Location Unit Letter <u>L</u> : <u>1980</u> feet from the <u>South</u> line and <u>990</u> feet from the <u>West</u> line Section <u>8</u> Township <u>18S</u> Range <u>35E</u> NMPM County <u>LJA</u>	7. Lease Name or Unit Agreement Name <u>STATE AF</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	8. Well Number <u>3</u>
	9. OGRID Number <u>222759</u>
	10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- DOWNHOLE COMMINGLE
- PLUG AND ABANDON
- CHANGE PLANS
- MULTIPLE COMPL

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING/CEMENT JOB
- ALTERING CASING
- P AND A

OTHER:

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Run casing scraper IN hole & back out
Run Tubing with 4" Arrowset packer nickel plated plastic coated
set packer at approx 9810
Do pre test on packer
Rig pulling unit down

CHART TEST WITNESSED BY
GEORGE BOWER, OCD
10/3/2017

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER DATE 10-2

Type or print name JIM GAURE E-mail address: JIM@THESTANDARDENERGY.COM PHONE: 575-393-8352

APPROVED BY: [Signature] TITLE AO/II DATE 10/10/2017
Conditions of Approval (if any):