

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised July 18, 2013

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

**HOBBS OCD**

|                                                                                                     |
|-----------------------------------------------------------------------------------------------------|
| WELL API NO.<br>30-025-23755                                                                        |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.                                                                        |
| 7. Lease Name or Unit Agreement Name<br>State B AC 1                                                |
| 8. Well Number 004                                                                                  |
| 9. OGRID Number 305911                                                                              |
| 10. Pool name or Wildcat<br>North Bagley Penn Pool                                                  |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.)<br>4254' GR                                      |

**NOV 8 9 2017**  
**RECEIVED**

SUNDRY NOTICES AND REPORTS ON WELLS  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other

2. Name of Operator  
EnergyQuest II, LLC

3. Address of Operator  
4526 Research Forest Dr., Ste. 200, The Woodlands, TX 77381

4. Well Location  
 Unit Letter J : 1980 feet from the SOUTH line and 1850 feet from the EAST line  
 Section 4 Township 12S Range 33E NMPM LEA County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

|                                               |                                                                                                                                                                                                           |                                                                                                                                                                                                      |                                                                                         |
|-----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|
| INT TO P&A<br>P&A NR <u>PM</u><br>P&A R _____ | OF INTENTION TO:<br><input type="checkbox"/> PLUG AND ABANDON<br><input type="checkbox"/> CHANGE PLANS<br><input type="checkbox"/> MULTIPLE COMPL<br><input type="checkbox"/><br><input type="checkbox"/> | SUBSEQUENT REPORT OF:<br><input type="checkbox"/> REMEDIAL WORK<br><input type="checkbox"/> COMMENCE DRILLING OPNS.<br><input type="checkbox"/> CASING/CEMENT JOB<br><input type="checkbox"/> OTHER: | <input type="checkbox"/> ALTERING CASING<br><input checked="" type="checkbox"/> P AND A |
|-----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- |                                                               |                                                                                          |
|---------------------------------------------------------------|------------------------------------------------------------------------------------------|
| 1. MIRU P&A equipment                                         | 11. Perforated at 2,500'                                                                 |
| 2. TIH w/packer and workstring                                | 12. Mixed and pumped 40 sx plug. WOC. Did not tag cement                                 |
| 3. Load hole with 9.5 ppg brine                               | 13. Called OCD Mark Whitaker                                                             |
| 4. Set packer, tested casing to 500 psi                       | 14. Mixed and pumped 40 sx plug. WOC. Tagged cement at 2,180'                            |
| 5. Unable to inject into perms, held 1,500 psi                | 15. Perforated at 1,700'                                                                 |
| 6. Set CIBP at 8,120'. Capped with 25 sx                      | 16. Mixed and pumped 40 sx plug. WOC. Tagged cement at 1,500'                            |
| 7. Perforated at 5,200'                                       | 17. Perforated at 423'                                                                   |
| 8. Mixed and pumped 30 sx plug. WOC. Tagged cement at 5,000'  | 18. Mixed and pumped 160 sx. Circulated cement thru 8-5/8", 13-3/8" 5-1/2" full.         |
| 9. Perforated at 3,908'                                       | 19. Cut wellhead. Mixed and pumped 10 sx to load all casings. Installed dry hole marker. |
| 10. Mixed and pumped 40 sx plug. WOC. Tagged cement at 3,800' |                                                                                          |

09/15/2017

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

Restoration Due By 09-14-2018

Spud Date:

4/23/71

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debra Moore TITLE Production Analyst DATE 11/27/2017

Type or print name Debra Moore E-mail address: debra.moore@energyquest.us PHONE: 281-875-6200

**For State Use Only**

APPROVED BY: Mark Whitaker TITLE P.E.S. DATE 11/29/2017

Conditions of Approval (if any):