

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised July 18, 2013

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-34220
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Shahara State Unit
8. Well Number 100
9. OGRID Number 305911
10. Pool name or Wildcat Maljamar Grayburg San Andres

SUNDRY NOTICES AND REPORTS OF WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
EnergyQuest II, LLC

3. Address of Operator
4526 Research Forest Dr., Ste 200, The Woodlands, TX 77381

4. Well Location
 Unit Letter E : 1330 feet from the North line and 140 feet from the West line
 Section 16 Township 17S Range 33E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4198 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> CLOSED-LOOP SYSTEM <input type="checkbox"/> OTHER: <input type="checkbox"/>	INT TO PA P&A NR <u>Pm</u> P&A R _____	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>
--	---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- MIRU P&A equipment. POOH w/production equipment.
- Set cast iron bridge plug @ 4,200'. Pressure test to 500 psi for 15 minutes. Cap w/25 sx Class C cmt.
- Circulate hole with 10.5 mud laden fluid
- Spot 25 sx cmt. @ 2,600' to 2,350'.
- Spot 25 sx cmt. @ 1,550' to 1,300'.
- Spot 65 sx cmt. from 571' to surface.
- Cut off wellhead, verify cmt. to surface, weld on dry hole marker.

8/11/17

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.
 Restoration Due By 8-10-2018

Spud Date: 01/15/98

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debra Moore TITLE Production Analyst DATE 11/14/2017

Type or print name Debra Moore E-mail address: debra.moore@energyquest.us PHONE: 281-875-6200

For State Use Only

APPROVED BY: Mah Whitaker TITLE P.E.S. DATE 11/29/2017

Conditions of Approval (if any):