Summit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resource	Form C-103 May 27, 2004					
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, witherars and Natural Resource	WELL API NO.					
District II	OIL CONSERVATION DIVISION	N 30-025-22621					
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease					
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE X  6. State Oil & Gas Lease No.					
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Sainta 1 C, 14141 67303						
87505		029102					
	FICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name					
	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	BAKER					
PROPOSALS.)	Con Wall Code	0. 777 11 37 . 1					
1. Type of Well: Oil Well \(\bar{X}\) 2. Name of Operator	Gas Well _ Other	8. Well Number 002  9. OGRID Number					
MOMENTUM OPERATING	CO, INC	196069					
3. Address of Operator	The state of the s	10. Pool name or Wildcat					
PO BOX 578 ALBA	NY, TX <sup>2</sup> 76430	DRINKARD					
4. Well Location							
Unit Letter A	: 330 feet from the NORTH line at	nd 350 feet from the EAST line					
Section 26	Township 22-S Range 37-	E NMPM County LEA					
*	11. Elevation (Show whether DR, RKB, RT, G	R, etc.)					
	3325 KB						
Pit or Below-grade Tank Application							
Pit type Depth to Grounds							
Pit Liner Thickness: mi		bls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF I	NTENTION TO:	SUBSEQUENT REPORT OF:					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK DALTERING CASING DALTERING DALTERING DALTERING DALTERING DALTERING DALTERING DALTERING DALTER							
TEMPORARILY ABANDON	•	CE DRILLING OPNS. P AND A					
PULL OR ALTER CASING	MULTIPLE COMPL CASING/C	EMENT JOB					
OTHER:	☐ OTHER:						
		ails, and give pertinent dates, including estimated date					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.							
MOVE IN PULLING U	NIT AND REVERSE UNIT. SHOOT TU	BING OFF 1732'. WASH-OVER AND					
	50'. RUN BOND LOG 1850'. SET						
CEMENTERS-TICKET							
CLEAN UP LOCATION	AND PUT INTORY HOLE MARKER.						
Approved as to plugging of the Well Bore.  Liability under bond is retained until surface restoration is completed.							
3//0/00		(3/10) . <b>(5/2</b> )					
		4					
Approved as to plugging of the Well Bore.							
Liability under bond is retained until							
surface restoration is completed.							
	•						
		2400109					
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.							
SIGNATURE BOLL	devele TITLE SECRETAR						
Type or print name BOB TIDW	ELL E-mail address:	Telephone No. (325)762-3331					
For State Use Only	. A	Telephone 140. (325)/62=3331					
91							
APPROVED BY APR 1 9 2000							
Conditions of Approval (if any):	Wink TITLE HELD REPRE	SENTATIVE IVSTAFF MEDITE APR 1 9 2006					

· OIL WELL CEMENTING • ACID SERVICES

• TURNKEY ABANDONMENTS

P.O. BOX 61193 PISING STAR Middland, Texas 79711

STAR Office # 432-617-0114

Fax # 432-339-0140

## **RISING STAR JOB REPORT**

4370

				WELL NO	MBER	DATE		
CUST NAME	RACRACATE		DATING GO					
147AINE	MOMENTUM OPERATING CO		LEASE	2	March 16, 2006			
ADDRESS	РО ВОХ			LEASE	BAKER	RIG CONTRACTOR MOMENTUM OPERATING		
				COUNTY		STATE		
CITY STATE &	<del></del>			-	LEA	NM		
	ALBANY	TX	76430	1	SERVICE			
71				PTA				
Time	CALL OUT 5	25.125		Rem	arks			
5:30AM 7:30AM	CALL OUT FO		N 045554455					
9:19AM	ARRIVE ON LOCATION - SAFETY MEETING-SPOT EQUIPMENT- RIG UP & TEST H20							
9:22AM	PUMP 7 BBLS OF FAV AHEAD @ 2 BPM @ 800 PSI							
	5.5 BBLS OF FAV CONE @ 2 BPM @ 1000 PSI							
9:23AM	7 BBLS OF FW GONE @ 2 BPM @ 1000 PSI							
0.201	START ON LD CMT PUMP/200 SKS OF CLASS "C" 3% SALT,3/10% C-16A, 5/10# C-41P (MIXED @ 14.8#							
9:33AM	PER GAL=47 BBLS OF SLUKRY) @ 2 BPM @ 1000 PSI 20 BBLS OF LD CMT GONE @ 2.1 BPM @ 1000 PSI							
9:38AM	30 BBLS OF LD CMT GONE @ 2.1 BPM @ 1000 PSI							
9:46AM	45 BBLS OF LD CMT GONE @ 2.2 BPM @ 1000 PSI							
9:47AM	47 BBLS OF LD CMT GONE @ 2.2 BPM @ 1000 PSI							
9:47AM	START ON MIDDLE CMT PUMP 200 SKS) OF CLASS "C"W/2% CACL2, 5/10# C-41P (MIXED @ 14.8# PER							
	GAL=47 BBLS OF MID CMT SLURRY) @ 2.2 BPM @ 800 PSI							
9:51AM	10 BBLS OF MID CMT GONE @ 2.3 BPM @ 800 PSI							
9:56AM	20 BBLS OF MID CMT GONE @ 2.3 BPM @ 800 PSI							
10:01AM	30 BBLS OF MID CMT GONE @ 2.3 BPM @ 800 PSI							
10:08AM	47 BBLS OF MID CMT GONE SHUT DOWN AND S/O OF RET							
10:26AM	START ON TAIL CMT PUMP 131 SKS OF CLASS C"W/ 5/10# C-41P (MIXED @ 14.8# PER GAL=31 BBLS							
	IOF TAIL CMT (@ 2 BPM @ 0 PSI							
10:35AM	14 BBLS OF TL CMT GONE @ 2 BPM @ 0 PSI							
10:40AM	22.5 BBLS OF TL CMT GONE @ 2 BPM @ 50 PSI							
10:41AM	25.5 BBLS OF TL CMT GONE @ 2 BPM @ 100 PSI							
10:44AM	30 BBLS OF TL CMT GONE @ 2 BPM @ 200 PSI							
10:45AM	31 BBLS OF TL CMT GONE SHUT DOWN CMT CIRCULATED TO PIT							
I I SUPM	POOH AND TOP OUT WELL HEAD W/ 25 SKS OF CMT =5.8 BBLS							
	DI FIM ADOLES FOUR							
12:00PM	BLEW ABOUT 5 SKS OF CMT ON GROUND FOR DRY HOLE MARKER SHUT DOWN WASH UP PUMP							
12:00PM	RIG DOWN							
	RELEASED							
	· _ · · · · · · · · · · · · · · · · · ·			·				
		· · · · · · · · · · · · · · · · · · ·						
		<del></del>						
	THANK YOU FOR USING RISING STAR SERVICES							
	TRAVIS A. JENSEN & CREW							
SERVICE	DVIOL DEDOCATION							
SERVICE REPRESENTATIVE: CUST				CUSTON	ER REPRESEN	TATIVE:		
TRAVIS A. JENSEN			LONI					