District I 1625 N. French Dr., Hobbs, NM 88240	State of New Mexico	SIS	Form C-101
Phone: (575) 393-6161 Fax: (575) 393-0720 <u>District II</u> 811 S. First St., Artesia, NM 88210	Energy Minerals and Natural Resource	S	Revised July 18, 2013
Phone: (575) 748-1283 Fax: (575) 748-9720 District III	<b>Oil Conservation Division</b>		AMENDED REPORT
1000 Rio Brazos Road, Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170 District IV	1220 South St. Francis Dr.		
1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462	Santa Fe, NM 87505		

# APPLICATION FOR PERMIT TO DRILL, RE-ENTER, DEEPEN, PLUGBACK, OR ADD A ZONE

Occidental Permian LTD Operator Name and Address						45	<sup>2</sup> OGRID Number		
PO Box 429	94						15	7984	
Houston, T	X 77210						30-025-	<sup>3</sup> API Number	14609
<sup>4</sup> Property Code 19552 South Hobbs G/SA Unit						275 Well	No.		
				7. St	Irface Location	n			
UL - Lot E	Section 10	Township 19S	Range 38E	Lot Idn	Feet from 1797	N/S Line N	Feet From 1051	E/W Line W	County Lea
				<sup>8</sup> Propose	ed Bottom Hol	e Location			
UL - Lot F	Section 10	Township 19S	Range 38E	Lot Idn	Feet from 1439	N/S Line N	Feet From 2476	E/W Line W	County Lea
				<sup>9.</sup> Pc	ol Informatio	n			
			Но		<sub>Name</sub> g - San Andres				Pool Code 31920

#### **Additional Well Information**

New Drill		Well Type Inj	<sup>13.</sup> Cable/Rotary	<sup>14</sup> Leas Sta		<sup>15</sup> Ground Level Elevation 3605
<sup>16</sup> Multiple	<sup>17</sup> . Pro	oposed Depth	<sup>18.</sup> Formation	<sup>19.</sup> Cont	ractor	<sup>20</sup> . Spud Date
N		6000	San Andres			06/01/2018
Depth to Ground water		Distance fro	m nearest fresh water well		Distance to nearest surface water	

### We will be using a closed-loop system in lieu of lined pits

### <sup>21.</sup> Proposed Casing and Cement Program

	1		reporte choing and			
Туре	Hole Size	Casing Size	Casing Weight/ft	Setting Depth	Sacks of Cement	Estimated TOC
Surf	12.25	9.625	36	1700	690	0
Prod	8.75	7	26	6000	1200	0
		Casin	g/Cement Program: A	dditional Comments		

22. Proposed Blowout Prevention Program						
Туре	Working Pressure	Test Pressure	Manufacturer			
Annular	5000	3000				

<sup>23.</sup> I hereby certify that the information given above is true and complete to the best of my knowledge and belief.	OIL CONSERVATION DIVISION	
I further certify that I have complied with 19.15.14.9 (A) NMAC 🔀 and/or 19.15.14.9 (B) NMAC 🔀, if applicable.	Approved By:	
Signature: April Hood	Many Dotrolaum Engineer	
Printed name: April Hood	Title: Petroleum Englicer	
Title: Regulatory Specialist	Approved Date: 03/14/18 Expiration Date: 03/14/20	
E-mail Address: April_Hood@Oxy.com	/////	
Date: 03/14/2018 Phone: 713-366-5771	Conditions of Approval Attached See Attached	

# **Conditions of Approval**

#### CONDITIONS OF APPROVAL

API #	Operator	Well name & Number
30-025-44609	Occidental Permian LTD	South Hobbs G/SA Unit # 275

Applicable conditions of approval marked with XXXXXX

# Administrative Orders Required

XXXXXXXX	If within City Limits No Pits – Must use close loop	
XXXXXXXX	Will require administrative order for injection or disposal prior to injection or disposal	
)ther wells		

# Drilling

XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface,
	the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in
	cement the water protection string

# Casing

SURFACE CASING - Cement must circulate to surface
PRODUCTION CASING - Cement must circulate to surface
If cement does not circulate to surface, must run temperature survey or other log to determine top of cement
South Area
Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water

#### Completion & Production

XXXXXXX	Must notify Hobbs OCD office prior to conducting MIT (575) 393-6161 ext. 114
XXXXXXX	Must conduct & pass MIT prior to any injection

# Lost Circulation

XXXXXXX	Must notify OCD Hobbs Office if lost circulation is encountered at 575-370-3186
Stage Tool	

XXXXXXX	Must notify OCD Hobbs Office prior to running Stage Tool at 575-370-3186
XXXXXXX	If using Stage Tool on Surface casing, Stage Tool must be greater than 350' and a minimum 200 feet above surface shoe.
XXXXXXX	When using a Stage Tool on Intermediate or Production Casing Stage must be a minimum of 50 feet below previous casing shoe.