

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-25256
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator CROSS TIMBERS ENERGY, LLC		6. State Oil & Gas Lease No.
3. Address of Operator 400 W 7TH ST, FORT WORTH, TX 76102		7. Lease Name or Unit Agreement Name PENNZOIL PENNZOIL MERIT STATE
4. Well Location Unit Letter H : 1980 feet from the N line and 660 feet from the E line Section 18 Township 17S Range 34E NMPM County LEA		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4110' GL		9. OGRID Number 298299
		10. Pool name or Wildcat VACUUM; ABO, NORTH

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK	INT TO P&A ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPN:	P&A NR _____
PULL OR ALTER CASING ☐	MULTIPLE COMPL ☐	CASING/CEMENT JOB	P&A R _____
DOWNHOLE COMMINGLE ☐			
CLOSED-LOOP SYSTEM ☐			
OTHER: ☐		OTHER:	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

APPROX 3/28/18:

RU and POOH w/ tubing & rods.

Set 5K CIBP @ 8790', dump bail 35' of cement on top. Pressure test to 500 psi for 30 minutes.

Set 5K CIBP @ 4750', dump bail 35' of cement on top. Pressure test to 500 psi for 30 minutes.

Cut 5-1/2" casing at 2,000' and retrieve out of hole.

Spot 10' of cement from 1,990' - 2,000'. Pressure test to 500 psi for 30 minutes.

RIH w/ wireline and shoot squeeze holes in 8-5/8" casing @ 400'.

Set Cement Retainer @ 250'. Cement with 50 sx Class C. Leave 50' cmt on top of retainer.

Pressure test to 500 psi for 30 minutes.

Fill 8-5/8" casing with cmt from 50' to sfc.

Cut off Wellhead.

Verify Cmt to Surface all strings

Spud Date:

04/14/1976

Rig Release Date:

- ① CIRC MLF.
- ② Pressure test csg.
- ③ Spot 25 sx cmt at 6790'
- ④ Spot 25 sx cmt at 4785' WOC & TAG
- ⑤ Spot 25 sx cmt at 3311' WOC & TAG
- ⑥ Spot 25 sx cmt at 2700'
- ⑧ Spot 30 sx cmt at 1650'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Connie Blaylock TITLE REGULATORY TECH DATE 03/15/2018

Type or print name CONNIE BLAYLOCK E-mail address: cblaylock@mspartners.com PHONE: 817-334-7882

For State Use Only

APPROVED BY: Mark Whittem TITLE Petroleum Engr. Specialist DATE 03/19/2018

Conditions of Approval (if any):

- ③ Spacer Plug
- ④ Shoe Plug

- ⑤ Squeeze holes
- ⑥ Base Salt
- ⑧ Top Salt

C103 INTENT TO P&A EXPIRES
3/19/2019

mb

CURRENT & PROPOSED WELLBORE SCHEMATICS

Jobs

Type	Summary
Well Name	PENNZOIL MERIT STATE 1
API#	3002525256
County	Lea
State/Province	New Mexico
Field Name	VACUUM
Location	1980 FNL & 660 FEL
Township	17S
Range	34E
Section	18
Latitude (")	32° 50' 12.11" N
Longitude (")	103° 35' 37.356" W
Original KB Elevation (ft)	4,128.00
Gr Elev (ft)	4,110.00
KB-Ground Distance (ft)	18.00
Spud Date	4/14/1976

Vertical - Original Hole, 3/21/2018

