

## District I

1625 N. French Dr., Hobbs, NM 88240

## District II

1301 W. Grand Ave., Artesia, NM 88210

## District III

1000 Rio Brazos Rd., Aztec, NM 87410

## District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.	30-025-10229
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Thomas Long	
8. Well Number	5
9. OGRID Number	012024
10. Pool name or Wildcat Penrose-Skelly Grayburg	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐2. Name of Operator  
John H. Hendrix Corporation3. Address of Operator P. O. Box 3040  
Midland, TX 79702-30404. Well Location  
Unit Letter N : 660 feet from the South line and 1980 feet from the West line  
Section 11 Township 22S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐Pit type Steel Depth to Groundwater 65 Distance from nearest fresh water well 500 Distance from nearest surface water 71000Pit Liner Thickness: mil Below-Grade Tank: Volume bbbs; Construction Material 

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: Add perms. & return to production ☒

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☐CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Drill out CIBP at 3650' and clean out to 3788'.

2. Reperforate 3551 - 3770'.

3. Acidize &amp; test.

4. Return to producing status.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

Ronnie H. Westbrook

TITLE Vice President

DATE 04/19/2006

Type or print name Ronnie H. Westbrook

E-mail address:

Telephone No. (432)684-6631

For State Use Only

APPROVED BY:

TITLE

PETROLEUM ENGINEER

DATE

APR 25 2006

Conditions of Approval (if any):