Submit 1 Copy To Appropriate District	State of New Me	xico	Form C-103	
Office  District I - (575) 393-6161  HOBBS OFF, Minerals and Natural Resources  1625 N. French Dr., Hobbs, NM 88240		ral Resources	Revised July 18, 2013 WELL API NO. 30-025-27682	
District II – (575) 748-1283 OIL CONSERVATION DIVISION				
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 JUL 1 2 2018 CONSERVATION DIVISION District III - (505) 334-6178 1220 South St. Francis Dr.		icis Dr.	5. Indicate Type of Lease  STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 8/410			STATE 6. State Oil & Gas	
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, RECEIV 87505	ED '		o. State Sh & Sas	Elease 1 to
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Lea Fee	
PROPOSALS.)		8. Well Number 2		
1. Type of Well: Oil Well Gas Well Other Other  2. Name of Operator			9. OGRID Number	
Basic Energy Services LP.			246368	
3. Address of Operator 801 Cherry Street Suite 2100 Fort Worth TX 76102			10. Pool name or Wildcat るいか、SA	
4. Well Location			<b>3</b> 00=	)
Unit Letter A: 850 feet from the North line and 950 feet from the East line				
Section 17 Township 23S Range 27E NMPM County Lea				
11.	Elevation (Show whether DR)	RKB, RT, GR, etc.)		
12. Check Appro	priate Box to Indicate Na	ture of Notice, R	Report or Other D	ata
• •	-		-	
NOTICE OF INTENTION TO: SUB- PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WOR			BSEQUENT REPORT OF: RK	
TEMPORARILY ABANDON			_	P AND A
PULL OR ALTER CASING			ΓJOB □	
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM				
CLOSED-LOOP SYSTEM   OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
The purpose of the remedial workover will to be clean out fill that has accumulated in the bottom section of the well bore. Estimated start date will be Monday July 16th 8am. Rig will move in and rig up with BoP. Tubing will be pulled and inspected. Run back in with work				
string and bit and clean out the well bore to 5500'. Once the well is flowed back and circulated clean an acid job will follow. Work string				
will be pulled and the production packer and tubing will be ran back in the hole and set.				
	Section of the	The same of the sa	and the same of th	SWD-291
보다 하나 하나 하나 하나 하나 하나 하나 하나 하는 사람이 있다. 難				
Condition of Approval: notify				
OCD Hobbs office 24 hours				
prior of running MIT Test & Chart				
Spud Date:	nia natara na			] .
Spud Date:	Rig Release Dat	e:		_
_				
hereby certify that the information above	is true and complete to the bes	st of my knowledge	and belief.	
SIGNATURE DATE 7-10-18  GOOM, PRITCHETT @ DIVINE 422 212 ((1))				
Type or print name Gray Te	ではなす E-mail address:	GARY, PRITC	·からアグ	NE: 432-313-6/-41
For State Use Only	D D D D D D D D D D D D D D D D D D D	V I	WIVE STATE OF THE	1304 3210 40-11
APPROVED BY: Wally DIOWN FITTLE HO/I DATE 7/12/2018				
APPROVED BY: DATE 1/2/2010  Conditions of Approval (if any):				
•				