

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-025-01931
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	L0-4426
7. Lease Name or Unit Agreement Name	Northeast Kemnitz
8. Well Number	#2
9. OGRID Number	228937
10. Pool name or Wildcat	Kemnitz; Lower Wolfcamp
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	4100'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator: Matador Production Company

3. Address of Operator: 5400 LBJ Freeway Suite 1500
Dallas TX 75240

4. Well Location
Unit Letter G, 1980 feet from the NORTH line and 1980 feet from the EAST line
Section 22 Township 16S Range 34E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4100'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT

- REMEDIAL WORK
COMMENCE DRILLING OPNS. INT TO P&A ☒
CASING/CEMENT JOB P&A NR ☐
P&A R ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Safety mtg, MIRU, Kill well, ND WH, NU BOPs

1. TIH w/ tbq and spot 25 sx Cl H cmt on top of CBP @ 11,705'. WOC & Tag. TOOH.
2. Set CIBP @ 10725'. TIH w/ tbq and spot 25 sx Cl H cmt on top of CIBP. WOC & Tag. PU.
3. Perf @ 7970' & Sqz 35 sx Cl H cmt. WOC & Tag. PU.
4. Perf @ 4664' & Sqz 35 sx Cl C cmt. WOC & Tag. PU.
5. Perf @ 2860' & Sqz 35 sx Cl C cmt. WOC & Tag. PU.
6. Perf @ 1600' & Sqz 35 sx Cl C cmt. WOC & Tag. PU.
7. Perf @ 367' & Sqz cmt to surface.
8. Cut off wellhead and install above ground marker per NMOCD specifications.

Mud laden fluid mixed at 25sx/100 bbls will be spotted between each plug.

*Notify NMOCD office minimum 24 hours prior to Rig Up.


Spud Date:

1960

NOTIFY OCD 24 HOURS PRIOR TO
BEGINNING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE Engineer

DATE 7/27/18

Type or print name Chris Villarreal


cvillarreal@matadorresources.com

E-mail address:

PHONE: (972) 371-5471

For State Use Only

APPROVED BY:



TITLE P.E.S.

DATE 08/07/2018

Conditions of Approval (if any):

C103 INTENT TO P&A EXPIRES
1 YEAR FROM DATE OF APPROVAL

Well originally drilled to 10850' in 1960. Found to be dry & P&A'd in July 1960. Reentered & deepened to 11585' in 1961, found to be dry and P&A'd. Well reentered again in 1976 and drilled to 13450'.