District1 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 383-6161 Fax: (575) 383-0720 District11 811 S. First St., Artasia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District11 1000 Rio Brazos Road, Aztac, NM 87410 Phone: (505) 334-5178 Fax: (505) 334-6170 District1N 1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462	State of New Mexico Energy Minerals and Natur Resources Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505	
APPLICATION FOR PERMIT T	O DRILL, RE-ENTER, DEEPEN, P	LUGBACK, OR ADD A ZONE
<sup>1</sup> Operator Name and Address		<sup>2</sup> OGRID Number
JOINT RESOURCES COMPANY 5416 Birchman Avenue		372938
Fort Worth, TX 76107		30-025- 4 5 106
I designed and the second s		

#### Property Code <sup>5</sup> Property Name COMMANDER 004H <sup>7.</sup> Surface Location N/S Line UL - Lot Section Township Range Lot Idn Feet from Feet From E/W Line County 17S 700 39E М 31 S 1310 w Lea \* Proposed Bottom Hole Location Section Township Range Lot Idn Feet from N/S Line Feet From E/W Line County t مراد UL ŔΜ 6 18S 39E 100 S 1320 W Lea

		* Pool Information	on and a second s	
Pool Name CARTER;SAN AND	RES, SOUTH			Pool Code 10070
		Additional Well Inform	mation	
11. Work Type	<sup>12</sup> Well Type	13 Cable/Rotary	14 Lease Type	<sup>16</sup> Ground Level Elevation

. <b>N</b>		0	R	F	)	3635'
<sup>18.</sup> Multiple No	<sup>17</sup> Proposed	Depth 10,896	<sup>18</sup> Formation San Andres	<sup>14</sup> Contractor Norton Ener	gy Drig	<sup>20</sup> Spud Date September, 2018
Depth to Ground water		Distance fro	m nearest fresh water well		Distance to	nearest surface water

We will be using a closed-loop system in lieu of lined pits

#### <sup>27</sup> Proposed Casing and Cement Program

Туре	Hole Size	Casing Size	Casing Weight/ft	Setting Depth	Sacks of Cement	Estimated TOC
Surface	12.250	9.625	40	2206	900	0
Production	8.75	5.5	20	10,993	2625	800
					,	

#### Casing/Cement Program: Additional Comments

May use a casing sleeve system.

#### <sup>22</sup> Proposed Blowout Prevention Program

Туре	Working Pressure	Test Pressure	Manufacturer
Double Ram	3000	3000	NL Shaffer

<ul> <li>I hereby certify that the information given above is true and complete to the best of my knowledge and belief.</li> <li>I further certify that I have complied with 19.15.14.9 (A) NMAC and and or 19.15.149 (B) NMAC [].</li> </ul>		OIL CONSERVATION DIVISION
and/or 19.15.149 (B) NMAC if Signature:	applicable.	Approved By:
Printed name: Rachelle Whiteman		Title: Petroleum Engineer
Title: Regulatory Analyst		Approved Date: 08/17/18 Expiration Date: 08/17/20
E-mail Address: rachelle@jointresources.com		
Date: August 16 2018	Phone: 817-289-1414	Conditions of Approval Attached

# See Att ci d **Condition of Approval**

Well No.

### CONDITIONS OF APPROVAL

· · · · · · · · · · · · · · · · · · ·		
Operator	Well name & Number	UDBES OCU
JOINT RESOURCES	COMMANDER # 004H	HO 172010
ns of approval marked with XXXXXX		RECEIVED
		RECL.
	JOINT RESOURCES	JOINT RESOURCES COMMANDER # 004H

XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in
	cement the water protection string

# Casing

XXXXXXX	SURFACE & PRODUCTION CASING - Cement must circulate to surface
XXXXXXXX	If cement does not circulate to surface, must run temperature survey or other log to determine top of cement
XXXXXXX	Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water

## **Lost Circulation**

[	XXXXXX	Must notify OCD Hobbs Office if lost circulation is encountered at 575-370-3186

# Water flows

XXXXXXX	Must notify OCD Hobbs Office of any water flow in the Salado formation at 575-370-3186. Report depth
	and flow rate.

# Stage Tool

XXXXXXX	Must notify OCD Hobbs Office prior to running Stage Tool at 575-370-3186
XXXXXXX	If using Stage Tool on Surface casing, Stage Tool must be greater than 350' from surface and a minimum 200 feet above surface shoe.
XXXXXXX	When using a Stage Tool on Intermediate or Production Casing Stage must be a minimum of 50 feet below previous casing shoe.
· · ·	

Pits

XXXXXXX	If using a pit for drilling and completions, must have an approved pit form prior to spudding the well

# **Completion & Production**

XXXXXXX	Will require a directional survey with the C-104
XXXXXXX	Operator shall notify appropriate District office when setting conductor pipe.
XXXXXXX	The Operator is to notify NMOCD by sundry (Form C-103) within ten (10) days of spudding a well.
XXXXXXX	It is the operator's responsibility to monitor cancellation dates of approved APDs. APD's are good for 2 years and may be extended for one year. Only one 1 year extension will be granted if submitted by C-103 before expiration date. After expiration date or after a 1 year extension must submit new APD.
XXXXXXX	If an APD expires and if site construction has occurred, site remediation is required.