

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd. Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy, Minerals and Natural Resources
HOBBS
OIL CONSERVATION DIVISION
AUG 22 2018
South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED

WELL API NO. 30-025-09247
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1506
7. Lease Name or Unit Agreement Name Sinclair "B" State
8. Well Number 4
9. OGRID Numer 873
10. Pool Name or Wildcat Jalmat Tansil Yates SRQ

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Apache Corporation

3. Address of Operator
303 Veterans Airpark Lane, Ste. 3000, Midland, TX 79705

4. Well Location
Unit Letter **H A** : **1650** feet from the **N** line and **990** feet from the **E** line
Section **3** Township **23S** Range **36E** NMPM County **LEA**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON

TEMPORARILY ABANDON CHANGE PLANS

PULL OR ALTER CASING MULTIPLE COMPL

DOWNHOLE COMMINGLE

CLOSED-LOOP SYSTEM

OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING/CEMENT JOB

OTHER:

INT TO P&A **PM**
P&A NR _____
P&A R _____

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram or proposed completion or recompletion.

Apache Corporation proposes to P&A the above mentioned well by the attached procedure. A closed loop system will be used for all fluids from this wellbore and disposed of required by OCD Rule 19.15.17.14 NMAC.

**NOTIFY OCD 24 HOURS PRIOR TO
BEGINNING PLUGGING OPERATIONS**

Spud Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Guinn Burks TITLE Sr. Reclamation Foreman DATE 8/15/18

Type or print name Guinn Burks E-mail add. guinn.burks@apachecorp.com PHONE: 432-556-9143

APPROVED BY: Mahe Whitaker TITLE P.E.S. DATE 08/22/2018

Conditions of Approval (if any):



WELL BORE INFO.

LEASE NAME	SINCLAIR B STATE
WELL #	4
API #	30-025-09247
COUNTY	LEA

0
333
665
998
1330
1663
1995
2328
2660
2993
3325


TOC @ 470'

11" Hole
8 5/8" 28# @ 1269'
w/ 500 sx CIRC

Loaded w/ Inhibited Fluid

6 3/4" Hole
5 1/2" 14# @ 3045'
w/ 600 sx, TOC @ 470'/TS

OPEN HOLE 3045'-3325'



Perfs in OH @ 3045'-3325'

TD @ 3325'



WELL BORE INFO.

LEASE NAME	SINCLAIR B STATE
WELL #	4
API #	30-025-09247
COUNTY	LEA

PROPOSED PROCEDURE

Cut off wellhead 3' below ground level. Verify cement to surface. Install P&A marker.

3. PUH & perf @ 250', Sqz 75 sx Class "C" cmt from 250' to surf. Attempt to CIRC 5 1/2" to surf. (Water Board)

2. PUH & spot 25 sx Class "C" cmt from 1380'-1130', WOC/TAG (Surf Shoe & Top of Salt)

1. MIRU P&A rig / RIH & set CIBP @ 3000'. RIH w/ tbg & CIRC w/MLF & spot 25 sx Class "C" cmt from 3000'-2750' (Yates & Base of Salt)

0
333
665
998
1330
1663
1995
2328
2660
2993
3325


TOC @ 470'

11" Hole
8 5/8" 28# @ 1269'
w/ 500 sx CIRC

Loaded w/ Inhibited Fluid

6 3/4" Hole
5 1/2" 14# @ 3045'
w/ 600 sx, TOC @ 470'/TS

OPEN HOLE 3045'-3325'



Perfs in OH @ 3045'-3325'

TD @ 3325'

Pressure test csg