

Lease # LC032096A Wells

LOCKHART A 27	1	3002506800	X
LOCKHART A 27	2	3002506801	X
LOCKHART A 27	3	3002506807	X
LOCKHART A 27	5	3002506803	X
LOCKHART A 27	6	3002506804	X
LOCKHART A 27	7	3002506806	X
LOCKHART A 27	8	3002506805	X
LOCKHART A 27	10	3002506795	X
LOCKHART A 27	12	3002506796	X
LOCKHART A 27	13	3002506799	X
LOCKHART A 27	14	3002532169	X
LOCKHART A 27	15	3002534171	X
LOCKHART A 27	16	3002534312	X
LOCKHART A 27	23	3002539114	X
LOCKHART A 27	26	3002539115	X
LOCKHART A 35	1	3002507030	X
LOCKHART A 35	2	3002507031	X
LOCKHART A 35	3	3002507032	X
LOCKHART A 35	5	3002539050	X
LOCKHART B 35	1	3002507029	X
LOCKHART B 35	2	3002507033	X
LOCKHART B 35	3	3002507034	X
LOCKHART B 35	4	3002507035	X
LOCKHART B 35	5	3002524858	X
LOCKHART B 35	9	3002539037	X

nmlc032096B

**Change of Operator
Conditions of Approval**

1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
2. Submit for approval of water disposal method.
3. Submit updated facility diagrams as per Onshore Order #3
4. This agency shall be notified of any spill or discharge as required by NTL-3A.
5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
7. Subject to like approval by NMOCD.
8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.

JAM 082918