

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised August 1, 2011

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-02139 ✓
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator State of New Mexico for Canyon E&P Company		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, NM 88249		7. Lease Name or Unit Agreement Name Artesia Metex Unit
4. Well Location Unit Letter <u>D</u> : <u>330</u> feet from the <u>North</u> line and <u>990</u> feet from the <u>West</u> line Section <u>30</u> Township <u>18S</u> Range <u>28E</u> NMPM <u>Eddy</u> County ✓		8. Well Number <u>031</u> ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 269864 ✓
10. Pool name or Wildcat Artesia QU-GB-SA ✓		11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

HOBBS OCD

OCT 30 2018

SEE ATTACHED

RECEIVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

**For State Use Only**

APPROVED BY: Mark Whitman TITLE P.E.S. DATE 10/30/2018

Conditions of Approval (if any):

**Plugging Report**  
**Artesia Metex Unit #31**  
**API 30-015-02139**

10/19/2018 Move in and rig up. Laid down 79 ¾" rods. Dug out wellhead. No surface head. Installed BOP and shut down.

10/22/2018 POOH with tubing and tally. 71 joints 2 3/8". Made gauge ring run to 1800'. Set CIBP at 1781'. Circulated MLF and tested casing. Casing good to 500#. Spotted 35 sx on top of CIBP. POOH and perforated casing at 542'. Established circulation. Fluid coming into cellar due to no surface head. Pumped cement down 4 ½" casing to perfs at 542' and up the annulus. Took 160 sx to get cement to surface.

10/23/2018 Rigged down. Dug out cellar and cut off wellhead. 1" 4 ½" X \* 5/8" annulus from 25' and filled up 4 ½" casing with 15 sx. Installed marker, cut off anchors and cleaned the pit.