

OCD-HOBBS
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMLC032581A
2. Name of Operator Southwest Royalties, Inc.		6. If Indian, Allottee or Tribe Name
3a. Address 6 Desta Drive, Ste 2100	3b. Phone No. (include area code) 432/688-3267	7. If Unit or CA/Agreement, Name and/or No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660' FSL & 1980' FEL Sec 13, T25S, R36E, Unit O		8. Well Name and No. Sholes A 5
		9. API Well No. 30 025 09759
		10. Field and Pool, or Exploratory Area Jalmat
		11. County or Parish, State Lea County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Notify BLM 24 hrs prior to P&A commencement.

- 1) MI & RU; NU BOP.
- 2) RIH w/tbg and tag CIBP set @ 3000' and topped w/1 sx cmt in 1980'.
- 3) Circ hole w/MLF (minimum of 9 PPG).
- 4) Spot 25 sx class "C" cmt on top of CIBP and across base of Tag CIBP, spot 35 sx cmt and tag. PUH and spot 5 sx cmt 60' - surface. RD MO. Clean and restore location.

NEED 100' plug @ 1500-1400' @ 9 5/8" CSG SHOE + TAG
 NEED 100' plug @ 400-500' @ 13 3/8" CSG SHOE + TAG
 Present wellbore schematic attached.

14. I hereby certify that the foregoing is true and correct	
Name (Printed/Typed) Dawn M. Howard	Title Operations Assistant
Signature	Date 4/7/06

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by _____	Title _____	Date _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office _____	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

GWW

SUBJECT TO
FEDERAL REQUIREMENTS
AND SPECIAL stipulations
ATTACHED

Sholes A #5
JALMAT, TANSILL, YATES
Lea Co., NM

P&A Procedure

API NO. : 30-025-09796


LEASE NO. 101796-003

LOC: 1980' FEL & 660' FSL, Sec. 13 T25S, R36E

WELLBORE DIAGRAM

ELEVATION

GL	
KB	
DF	3141'



11-20/30-99 set CIBP @ 2890' w/2 sx cement
7/14/94 Drill out CIBP's Squ perfs 2880-2928'
run sub pump put well on prod.
Perf. 2880-2928 50 shots (2/1/91)
Set CIBP @ 2936' 2/1/91
Set CIBP @ 2970' w/1 sx Cement on top (10/25/90)
Perf. 2976-86' (22 holes 11-10-80)
Set CIBP @ 3000' w/1 sx Cement on top (11/10/80)
Perf.: 3008-26 (72 holes)
Perf: 3034-44' Sqz w/50 sx (Oct. 1950)
Perfs: 2940-2960' (11/1/40)
Plug back to 3065' 11/1/40)
Plug Back to 3080' w/cemrnt; Perf 3070' 2 holes 10/17/40

Production Casing: 7" Set @ 3286' Cemented w/400 sx (1934)

Open Hole 3286 to 3344' PB to 3286' w/cement 3/3/36