

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised August 1, 2011

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-23309

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
State Land Section 32

8. Well Number: 9

9. OGRID Number: 16696

10. Pool name or Wildcat
Hobbs, Paddock

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other: -----

2. Name of Operator

Oxy USA Inc.

3. Address of Operator

Oxy USA Inc. PO Box 4294, Houston, TX, 77210

4. Well Location

Unit Letter J : 2130 feet from the South line and 1980 feet from the East Line

Section 32 Township 18-S Range 38-E NMPM Lea County Hobbs

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3637' (GL)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. POOH with Injection equipment.
2. Clean out to 5750'
3. RU WL Set CIBP @ ~5700',
Perf the following interval: 5345' to 5429'.
Dump Bail 5 sxs of cment on top of CIBP, RD WL
4. Acid treat new perfs with ~ 2500 gal of 15% HCL
5. RIH with production equipment
6. Return well to production

During this procedure we plan to use
the closed-loop system with a steel
tank and haul contents to the required
disposal per ODC Rule 19.15.17

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Engineer

DATE 12/13/2018

Type or print name

Carlos Restrepo

E-mail address carlos_restrepo@oxy.com

PHONE: 713-366-5147

For State Use Only

APPROVED BY:

TITLE

Petroleum Engineer

DATE

12/18/18

Conditions of Approval (if any):

Additional Data that would not fit on the form.