Submit 1 Copy To Appropriate District	()		c D	P
Office	State of N	lew Mexico nd Natural Resources		Form C-103 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals a		WELL API NO.	Revised suly 16, 2013
District 11 - (575) 748-1283	OIL CONSERV.	ATION BASION	Y 30-02	5-25951
811 S. First St., Artesia, NM 88210 District III ~ (505) 334-6178	1220 South	St. Francis Dr. JA		
1000 Río Brazos Rd., Aztec, NM 87410	Sonto Fa	NM 87505	STATE X	FEE
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Saina FC,	NW 07505	6. State Oil & Gas I	.ease No.
87505		Ka		
SUNDRY NOT (DO NOT USE THIS FORM FOR PROP	FICES AND REPORTS ON OSALS TO DRILL OR TO DEEPI			nit Agreement Name os E State
DIFFERENT RESERVOIR. USE "APPL			8. Well Number	
PROPOSALS.) 1. Type of Well: Oil Well 🔀	Gas Well 🔲 Other			32
2. Name of Operator		9. OGRID Number		
Co		217817		
3. Address of Operator	(10. Pool name or Wildcat		
	idge Pkwy Houston, TX 7	/ /0/9	Maljan	nar GB/SA
4. Well Location Unit Letter N :	660 feet from the S	iouthline and	1110 fast farmeder	Wast Bas
Section 13	_000icer from theS Township 17-S	Range 33-E	NMPM	
Section 15		ther DR, RKB, RT, GR, e		County Lea
		4131' GR		
12. Check	Appropriate Box to Ind	licate Nature of Notic	e, Report or Other D	ata
		121 511	BSEQUENT REPO	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WO		
				AND A
PULL OR ALTER CASING	MULTIPLE COMPL			
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM]			_
OTHER: 13. Describe proposed or com	nleted operations (Clearly	C OTHER:	and give nortinent dates	including actimuted data
of starting any proposed w	work). SEE RULE 19.15.7.1	4 NMAC. For Multiple C	Completions: Attach wel	lbore diagram of
proposed completion or re				
MIRU	. ND WH, NU BOP. POOH	w/ Prod. Fanin		
	BP @ 4365' - Circ hole w/		. Spot 25sx cmt @ 4365*	-4165'.
Spot 2	5sx cmt @ 3814' - 3614'		 Asset 	
	5sx cmt @ 3165' - 2565'. V			
	5sx cmt @ 1525' - 1325'. W	VOC-Tag	-	
	5sx cmt @ 466' – 3' I. Fill wellbore. Verify cmt @	a) surface in all annuli	n See	
	f WH & anchors. Install DH		Condition Alt	ach.
			- uons o	e'led
				Appro
			See Att Conditions of	· / · · va/
**A closed-loop system	will be used for all fluids from	n this wellbore and dispose		
-		p		
Spud Date:	Rig Re	elease Date:		
I hereby certify that the information	above is true and complete	to the best of my knowle	dge and belief.	
SIGNATURE		Agent – Basic Energy	Services DATE	1/11/10
Type or print nameGreg Bry	yant E-mail addro	255:	PHONE:	432-563-3355
For State Use Only		_		
APPROVED BY: Kerry 5 Conditions of Approval (if ey):	ortherTITLE	Compliance Of	ficer A DATE	1-18-19

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit



WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

.1

Date: 11/27/18

						Date: 11/27/	18	
RKB @ 4141'								
DF @ 4141	Martine reason	6 b c u c c						
GL @ 4131		Subarea :						
			Lease & Well No. : Phillips State E		32	• •		
154-5-6	to the	Legal Descriptio		Sec. IJN,	-1/5, 1	R-33E_660' FSL & 2310' FV	VL	
Surface		County :	LEA			State : New Mexico		
	8-5/8", 24#/ft to 416	Field : Date Spudded :	MALJAMAR (Caprock)		,,			
- 19 - 2	Cmt'd w/ 550 SX							
	TOC - Circ'd to surface Spot 35sx cmt @ 466'-3'	API Number :	30-025-25951					
	Shor 222X cuit (0 466 -2							
			454RSER	IHS_1075	GDS	RUSTLER	1.510	
			63YTEX	IHS_1025	GDS	YATES	2,840	
			4535 \% \	DIS_TOPS	GDS	SEVEN RIVERS	3.165	
			43QUEN			QUEEN	3,814	
			4535ADR	EKS_1075		SAN ANDRES	4,600	
	Spot 25sx cmt @ 1525'-1325' - Tag							
	spot 255x cmt @ 1525-1525 - 14g							
() () () () () () () () () ()								
	Production							
	4-1/2", 11.6#/ft to 4706							
	Cmt'd w/ 850 SX							
	TOC - Circ'd to surface							
	Spot 45sx cmt @ 3165'-2565' - Tag							
	Spot 25sx cmt @ 3814'-3614'							
	S							
N 😪								
	Spot 25sx cmt @ 4365'-4165'							
	Set CIBP @ 4365							
	C C							
= =	San Andres Perfd							
	4465' - 4573'							
	Grayburg Perf d							
	4652' - 4660'							
1210.20	PBTD @ 4692' (Tagged)							
	TD @ 4706',							

.

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. <u>Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent</u>. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.