

Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
pining (575) 202 (10) ueroy Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	30-025-28223
811 S. First St., Artesia, NM 88210 OIL CONSERVATION	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Do 6 2019	STATE FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. V-732-2
87505 RECEIVE	V-/32-2
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	New Mexico DL State 8. Well Number #1
PROPOSALS.)	8. Well Number #1
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator	9. OGRID Number
COG Operating, LLC	229137
3. Address of Operator	10. Pool name or Wildcat
600 W. Illinois Ave, Midland, TX 79701	Cruz Delaware
4. Well Location	
Unit Letter I: 1980 feet from the S line and 660	feet from the <u>E</u> line
Section 18 Township 23S Range 33E	NMPM County Lea
11. Elevation (Show whether DR, RKB) RT, GR, et 3705'	(c.)
3103	
12. Check Appropriate Box to Indicate Nature of Notice	e. Report or Other Data
	•
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO TEMPORARILY ABANDON CHANGE PLANS COMMENCE D	PRK ☐ ALTERING CASING ☐ ☐ RILLING OPNS.☐ P AND A ☐
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEME	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	_
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and the state of the s	and give nertinent dates, including estimated date
of starting any proposed work) SEF RIU F 19 15 7 14 NMAC For Multiple (ompletions: Attach wellhore disgram of
proposed completion or recompletion.	TAGY CLASSE LUDO NU TOOL
proposed completion or recompletion.	
1. Tag existing CIBP @ 8230'. SPOT 25 SX Class HCMT 50 4600 Base of SALT	
2. Set 5 ½" CIBP @ 5100'. Circ' hole w/ MLF. Pressure test csg. Spot 26 sx cmt @ 5100-4900'. WOC & Tag (8 5/8" Shoe).	
3. Perf & Sqz 50 sx cmt @ 2000 -1800'. WOC & Tag 2150 Top of SALT	
4. Perf & Sqz 130 sx cmt @ 650' to surface.	
5. Cut off well head, verify cmt to surface, weld on Below Ground Dry Hole M	larker.
Send bic ? B	efore Back Fill
	• • • • • • • • • • • • • • • • • • • •
	See Attached
Spud Date: Rig Release Date:	Conditions of Approval
	who of who al
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE AL O Suglava on TITLE Agent	DATE 2/28/2019
Type or print name Abigail Anderson E-mail address: Email address:	na associates com
Type or print name Abigail Anderson E-mail address:	PHONE: 432-580-7161
For State Use Only	
APPROVED BY: Yeurs Finting TITLE Conclusion D	Olives A DATE 3-8-19
APPROVED BY: Kerry Further TITLE Compliance Of Conditions of Approval (if any):	ALL DATE
· · · · · · · · · · · · · · · · · · ·	





GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.