State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE **OIL CONSERVATION DIVISION** WELL API NO. 1220 South St. Francis Dr. **DISTRICT I** 30-025-05483 1625 N. French Dr., Hobbs, NM 88240 Santa Fe, NM 87505 5. Indicate Type of Lease DISTRICT II STATE X 1301 W. Grand Ave, Artesia, NM 88210 6. State Oil & Gas Lease No. DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs Unit (G/SA) DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 24 1. Type of Well: 8. Well No. 231 Gas Well Oil Well X 9. OGRID No. 2. Name of Operator 157984 Occidental Permian Ltd. 10. Pool name or Wildcat 3. Address of Operator Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4. Well Location 23/0 Feet From The Line 2600 West Unit Letter Feet From The South **NMPM** County Range 37-E Section 18-S 24 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3667' GL Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well

Distance from nearest surface water Pit Type Depth of Ground Water Below-Grade Tank: Volume bbls; Construction Material Pit Liner Thickness ___ Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **CHANGE PLANS PLUG & ABANDONMENT TEMPORARILY ABANDON** COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB **PULL OR ALTER CASING Multiple Completion** OTHER: OTHER: Open Additional Perfs & Acid Treat Well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Pull ESP equipment 2. Run TDT/GR/CCL log from PBTD to 3300'. 3. Set CIBP @4225' 4. Perforate hole 4175-4190' @2 JSPF (22 holes) 5. Acid treat new perfs 6. Perforate hole 4140-54' @1 JSPF (15 holes) 7. Acid treat new perfs 8. Run ESP equipment I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below state tank has been/will be constructed or or an (attached) alternative OCD-approved , a general permit closed according to NMOCD guidelines plan **SIGNATURE** TITLE DATE 05/06/2006 Administrative Associate TYPE OR PRINT NAME Mendy A -mail address: Mendy johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY OC FIELD REPRESENTATIVE II/STAFF MANAGER CONDITIONS OF APPROVAL F ANY: