

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

DISTRICT I
1625 N. French Dr., Hobbs, NM 88240

DISTRICT II
1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO. 30-025-07663	
5. Indicate Type of Lease STATE ☒ FEE ☐	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit Section 9	
8. Well No. 75	
9. OGRID No. 157984	
10. Pool name or Wildcat Hobbs (G/SA)	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Occidental Permian Ltd.	
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323	
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> <u>660</u> Feet From The <u>East</u> Line Section <u>9</u> Township <u>19-S</u> Range <u>38-E</u> NMPM <u>Lea</u> County	
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3604' DF	
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	Multiple Completion ☐
OTHER: _____	OTHER: _____
REMEDIAL WORK ☒	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG & ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	
OTHER: _____	OTHER: _____

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU. Kill well. POOH w/tbg & ESP equipment.
2. Set pkr @3971'.
3. Spot 30.5 bbl 15% NEFE acid. Flush w/50 bbl 10# brine.
4. RU swab equipment. FL @300'. Swabbed back 24 bbl.
5. Pump 200 gal NALCO 6490 chemical in 100 bbl fresh water. Flush w/500 bbl fresh water.
6. RIH w/sub pump & tbg. Intake set @ 4007'.
7. RDPU. Clean & level location.

RUPU 04/20/06
RDPU 04/26/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Mendy A. Johnson TITLE Administrative Associate DATE 05/06/2006
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: Mendy_johnson@oxy.com TELEPHONE NO. 806-592-6280

For State Use Only
APPROVED BY Laurel W. Wank TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE _____
CONDITIONS OF APPROVAL IF ANY _____

MAY 10 2006