Submit One Copy To Appropriate District	State of New Me	vico	Form C-103
Office	Energy, Minerals and Natu		Revised November 3, 2011
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Dieigy, Minierals and Mata		WELL API NO.
District II	OIL CONSERVATION	DIVISION	30-025-39804
811 S. First St., Artesia, NM 88210 District III	1220 South St. Fran		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87		STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM		<i>(</i> .	6. State Oil & Gas Lease No.
87505	AND DEDODES ON WELLS	- Co 18	
SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.) 1. Type of Well: Oil Well Gas 2. Name of Operator	TO DRILL OR TO DEEPEN OR PLA	HE BACK TO 20	7. Lease Name or Unit Agreement Name NTRAL DRINKARD UNIT
DIFFERENT RESERVOIR. USE "APPLICATION OF THE PROPERTY OF THE P	ON FOR PERMIT" (FORM C-101)	SUCH 1	8. Well Number
PROPOSALS.)	: Well Other	MA. C	#440
2. Name of Operator	Wen Duner		9. OGRID Number
Chevron U.S.A Inc.		· Øy	4323
3. Address of Operator		9	10. Pool name or Wildcat
6301 Deauville Blvd., Midland, TX 797	706		DRINKARD
4. Well Location:			
Unit Letter_N_:959_feet from the <u>SOUTH</u> line and <u>2519</u> feet from the <u>WEST</u> line			
Section 29 Township 21-S Range 37-E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3467' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data P. 7.			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
1	LUG AND ABANDON 🔲	REMEDIAL WORK	
TEMPORARILY ABANDON			
PULL OR ALTER CASING M		CASING/CEMENT	JOB
OTHER:	П	⊠ Location is re	adv for OCD inequation after P&A
OTHER:			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE Katherine Papageorge TITLE Decommissioning Project Manager DATE 5.22.19			
TYPE OR PRINT NAMEKatherine Papageorge_E-MAIL: _Katherine.Papageorge@chevron.com PHONE:832-854-5291			
For State Use Only			
APPROVED BY: Key July	TITLE (moliano O.	ffice A DATE 5-30-19
- / - //			