#### **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

**SUNDRY NOTICES AND REPORTS ON WELLS** 

**OCD Hobbs** 

FORM APPROVED OMB NO. 1004-0137 expires: January 31, 2018

	Expues, Janu
~	Lease Serial No.
J.	Lease Sellal No.
	NMNM36Q16

	is idilii idi pioposeis lo	drill or to re-enter a	'' '-	6. If Is	ndian Allottee o	r Tribe Name	
abandoned we		6. If Indian, Allottee or Tribe Name					
SUBMIT IN	TRIPLICATE - Other Inst	ructions on page 2	Ö <del>BB3 (</del>	CD7. If U	Init or CA/Agree NM72609A	ement, Name and/o	r No.
. Type of Well Gas Well Otl	her		UN 1 0 201		l Name and No. RTH MADURO		
Name of Operator CIMAREX ENERGY COMPA	Contact: NY OF C <del>O</del> -Mail: DEYLER@	DAVID A EYLER MILAGRO-RES.COM	ECEIVE	9. AP	I Well No. -025-30267-0	00-S1	
a. Address 600 N MARIENFELD STE 60 MIDLAND, TX 79703	3b. Phone No. (include Ph: 432-687-3033		10. Field and Pool or Exploratory Area GEM-MORROW (GAS)				
. Location of Well (Footage, Sec., 7	)	P	11. Co	11. County or Parish, State			
Sec 20 T19S R33E SENE 23	10FNL 660FEL			LE	A COUNTY,	NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NAT	TURE OF NO	TICE, REPO	RT, OR OTH	ER DATA	
TYPE OF SUBMISSION			TYPE OF ACT	ION			
□ Notice of Intent	☐ Acidize	☐ Deepen	1	Production (Sta	rt/Resume)	☐ Water Shu	-Off
	☐ Alter Casing \	☐ Hydraulic Fr	acturing 🔲 F	Reclamation		■ Well Integrate	rity
Subsequent Report	Casing Repair	New Constru	action 🔲 F	Recomplete		□ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Aba	andon 🔲 🛚	Temporarily Al	bandon		
	Convert to Injection	Plug Back	_ v	Water Disposal			
3. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for the	ally or recomplete horizontally, ork will be performed or provide d operations. If the operation res bandonment Notices must be fik	give subsurface locations the Bond No. on file with sults in a multiple complet	and measured and BLM/BIA. Required tion or recompleti	d true vertical de uired subsequent on in a new inter	pths of all pertin reports must be rval. a Form 316	nent markers and zo filed within 30 day 60-4 must be filed o	ones. ys once
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for 104/14/19: SET 5-1/2"CIBP @ TO 750# - HELD OK; PUMP @ TO 750# - HEL	ally or recomplete horizontally, it will be performed or provide doperations. If the operation restandonment Notices must be file final inspection.  13.000'; CIRC_WELL; PL 60 SXS.CMT. @ 12.496'-1T. @ 11.014'; WOC X TACT. @ 7.929'-7,759'; D 5.260' - NOT FREE; PUID: CUT CSG. @ 3.280'-NGSCZ. HOLES @ 1.460'; A'O'(PER BLM); WOC.  D'; PERF_SQZ. HOLES @ 1.460'; A'O'(PER BLM); WOC.  D'; PERF_SQZ. HOLES @ 1.460'; A'O'(PER BLM); WOC.  TIPERF_SQZ. HOLES @ 1.460'; A'O'(PER BLM); WOC.	give subsurface locations the Bond No. on file with sults in a multiple completed only after all requirements of the Bond No. on file with the sults in a multiple completed only after all requirements of the subsurface of the su	and measured and BLM/BIA. Requision or recompletients, including recursive 13,000'-12,80 (CD BY BLM).  5,360'(PER B. SXS.CMT. @ IJ. RATE - PRUSEST. INJ. RAK CIRC. TO SI	d true vertical de uired subsequent on in a new interclamation, have be 100; PRES. TE 100; PRES. TE 100; PRES. UP TO 75  TE PRES. UP TO 75  TE PRES. URF. 25 SXS	pths of all pertin reports must be eval, a Form 316 been completed a RECLAM  BLM: WOC 360#X HOLD;  JP TO 750#  CMT. @	inent markers and zer filed within 30 days filed within 30 days filed within 30 days filed within 30 days filed within 50 days filed cand the operator had attracted a	ones. ys since s S
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for 1 04/14/19: SET 5-1/2"CIBP @ TO 750# - HELD OK; PUMP 04/18/19: PUMP 30 SXS.CM 04/22/19: PUMP 25 SXS.CM 04/23/19: PUMP 25 SXS.CM 04/23/19: TAG CMT. @ 2,865: PERE. PUMP 45 SXS.CMT. @ 1,510 04/25/19 TAG CMT. @ 1,080 X HOLD; PUMP 30 SXS.CM 63'-3'. 04/26/19: DIG OUT X CUT O	ally or recomplete horizontally, it will be performed or provided operations. If the operation restandonment Notices must be file final inspection.  13.000'; CIRC_WELL; PL. 60 SXS.CMT. @ 12,496-17. @ 11.014'; WOC X TACT. @ 7.929-7,759'; D. 5,260' - NOT FREE; PUP: CUT CSG. @ 3,280'-NCSQZ. HOLES @ 1.460'; ACT. @ 559'; WOC X TAG CIT. & Strue and correct.  Electronic Submission #For CIMAREX EN amitted to AFMSS for process.	give subsurface locations the Bond No. on file with sults in a multiple completed only after all requirements of the Bond No. on file with the sults in a multiple completed only after all requirements of the subsurface of the sults of the subsurface of the subsurf	and measured and BLM BIA Required in BLM Well Inforce, sent to the PEREZ on 04/29	d true vertical de uired subsequent con in a new interchamation, have to 100'; PRES. TE 100'; PR	pths of all pertin reports must be eval, a Form 316 been completed a RECLAM  BLM: WOC 350# HOLD;  JP TO 750#  CMI. @  LL BELOW GRECLAM  CEPTED	inent markers and zer filed within 30 day for 4 must be filed cand the operator had alarmon PROCE ATTACHED	DURE
Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for 104/14/19: SET 5-1/2"CIBP @ TO 750# - HELD OK; PUMP 04/18/19: PUMP 30 SXS.CM 04/22/19: PUMP 25 SXS.CM 04/22/19: PUMP 25 SXS.CM 04/24/19: TAG CMT. @ 4,899 TAG CMT. @ 2,865': PERF. PUMP 45 SXS.CMT. @ 1,511 (04/25/19) TAG CMT. @ 1,080 X HOLD; PUMP 30 SXS.CMT 63'-3'.  04/26/19: DIG OUT X CUT O	ally or recomplete horizontally, it will be performed or provided operations. If the operation restandonment Notices must be file final inspection.  13.000'; CIRC_WELL; PL. 60 SXS.CMT. @ 12,496-17. @ 11.014'; WOC X TACT. @ 7.929-7,759'; D. 5,260' - NOT FREE; PUP: CUT CSG. @ 3,280'-NCSQZ. HOLES @ 1.460'; ACT. @ 559'; WOC X TAG CIT. & Strue and correct.  Electronic Submission #For CIMAREX EN amitted to AFMSS for process.	give subsurface locations the Bond No. on file with the Bond No. on fi	and measured and BLM BIA Required in BLM Well Inforce, sent to the	d true vertical de uired subsequent con in a new interchamation, have to 100'; PRES. TE 100'; PR	pths of all pertin reports must be vival, a Form 316 peen completed a ST CSG. RECLAM  BLM: WOC: 0#XHOLD; UP-TO-750# CMI.@  LLBELOW GRECL.  DUE: 1023005E)	inent markers and zer filed within 30 day following the filed of and the operator had lation PROCE ATTACHED  SROUND AMATIC POR RECO	DURE
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for 1 04/14/19: SET 5-1/2"CIBP @ TO 750# - HELD OK; PUMP 04/18/19: PUMP 30 SXS.CM 04/22/19: PUMP 25 SXS.CM 04/23/19: CUT 5-1/2" CSG. @ 04/24/19: TAG CMT. @ 4.895 TAG CMT. @ 2,865". PERE. PUMP 45 SXS.CMT. @ 1,510 04/25/19 TAG CMT. @ 1,080 X.HOLD; PUMP 30 SXS.CMT. 63'-3".  04/26/19: DIG OUT X CUT O	ally or recomplete horizontally, it will be performed or provided operations. If the operation restandonment Notices must be file final inspection.  13.000'; CIRC_WELL; PL. 60 SXS.CMT. @ 12,496-17. @ 11.014'; WOC X TACT. @ 7.929-7,759'; D. 5,260' - NOT FREE; PUP: CUT CSG. @ 3,280'-NCSQZ. HOLES @ 1.460'; ACT. @ 559'; WOC X TAG CIT. & Strue and correct.  Electronic Submission #For CIMAREX EN amitted to AFMSS for process.	give subsurface locations the Bond No. on file with sults in a multiple completed only after all requirements of the Bond No. on file with the sults in a multiple completed only after all requirements of the subsurface of the sults of the subsurface of the subsurf	and measured and BLM BIA Required in BLM Well Inforce, sent to the PEREZ on 04/29	d true vertical de uired subsequent con in a new interchamation, have to 100'; PRES. TE 100'; PR	pths of all pertin reports must be eval, a Form 316 been completed a RECLAM  BLM: WOC: 0#XHOLD; UP TO 750# CMT. @  L BELOW G RECLAM  CEPTED 02366E	ATTACHED  SROUND  AMATIC  AMAT	DURE
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for 1 04/14/19: SET 5-1/2"CIBP @ TO 750# - HELD OK; PUMP 04/18/19: PUMP 30 SXS.CM 04/22/19: PUMP 25 SXS.CM 04/23/19: CUT 5-1/2" CSG. @ 04/24/19: TAG CMT. @ 4.89 TAG CMT. @ 2.865: PERE. PUMP 45 SXS.CMT. @ 1.51(04/25/19) TAG CMT. @ 1.080 X HOLD; PUMP 30 SXS.CM 63'-3'.  04/26/19: DIG OUT X CUT O 4.1 hereby certify that the foregoing in Command (Printed/Typed) DAVID A	ally or recomplete horizontally, it will be performed or provide d operations. If the operation restandanment Notices must be file final inspection.  13.000'; CIRC_WELL; PL 60 SXS_CMT_@ 12.496'-1T_@ 11.014'; WOC X TACT. @ 7.929'-7,759'; D 5.260' - NOT FREE; PU 9'; CUT CSG. @ 3.280'-NO SQZ. HOLES @ 1.460'; A'D'(PER BLM); WOC X TAG CIT CSG. WOC X TAG CSG. WOC X TAG CIT CSG. WOC X TAG CSG. WOC X TAG CIT CSG. WOC X TAG CSG. WOC X TAG CSG. WOC X TAG C	give subsurface locations the Bond No. on file with sults in a multiple completed only after all requirements of the Bond No. on file with the sults in a multiple completed only after all requirements of the sults	and measured and BLM/BIA. Requision or recompletients, including recom	d true vertical de uired subsequent on in a new interchamation, have be 100'; PRES. TE 100'; PRE	pths of all pertin reports must be vival, a Form 316 peen completed a RECLAM  BLM: WOC: RECLAM  BLM: WOC: OF THE PROPERTY OF THE PERCENTION OF THE PERCENTIO	inent markers and zer filed within 30 day fold within 30 day fold must be filed to and the operator had lation PROCE ATTACHED  SROUND AMATIC PASSES FOR RECO	DURE
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for 104/14/19: SET 5-1/2"CIBP @ TO 750# - HELD OK; PUMP @ TO 750# - HEL	ally or recomplete horizontally, it will be performed or provide d operations. If the operation restandanment Notices must be file final inspection.  13.000'; CIRC_WELL; PL 60 SXS_CMT_@ 12.496'-1T_@ 11.014'; WOC X TACT. @ 7.929'-7,759'; D 5.260' - NOT FREE; PU 9'; CUT CSG. @ 3.280'-NO SQZ. HOLES @ 1.460'; A'D'(PER BLM); WOC X TAG CIT CSG. WOC X TAG CSG. WOC X TAG CIT CSG. WOC X TAG CSG. WOC X TAG CIT CSG. WOC X TAG CSG. WOC X TAG CSG. WOC X TAG C	give subsurface locations the Bond No. on file with sults in a multiple completed only after all requirements of the Bond No. on file with sults in a multiple completed only after all requirements of the Bond No. 12.066'.  CMT. @ 10.790'(O)  MP 45 SXS.CMT. @ 10.790'(O)  MP 46 SXS.CMT. @ 10.790'(O)  MP 45 SXS.CMT. @ 10.790'(O)  MP 46 SXS.CMT. @ 10.790'(O)  MP 45	and measured and BLM/BIA. Requision or recompletients, including recom	d true vertical de uired subsequent on in a new interchamation, have be 100'; PRES. TE 100'; PRE	pths of all pertin reports must be reval, a Form 316 peen completed a RECLAM  BLM: WOC: 60#XHOLD; 1P-TO.750# CMI. @  LL BELOW GRECL.  DUE: 10 CEPTED 02300E)  WAY  UREAU OF LA	ATION PROCE ATTACHED  SROUND AMATIC  POR RECO  1 5 2019	DURE
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for 1 04/14/19: SET 5-1/2"CIBP @ TO 750# - HELD OK; PUMP 04/18/19: PUMP 30 SXS.CM 04/22/19: PUMP 25 SXS.CM 04/23/19: PUMP 25 SXS.CM 04/23/19: TAG CMT. @ 4.89 TAG CMT. @ 2.865: PERF. PUMP 45 SXS.CMT. @ 1.510 04/25/19 TAG CMT. @ 1.080 X HOLD; PUMP 30 SXS.CM 63'-3'.  04/26/19: DIG OUT X CUT O	ally or recomplete horizontally, rk will be performed or provided operations. If the operation restandonment Notices must be file final inspection.  13.000'; CIRC_WELL; PL. 60 SXS.CMT. @ 12,496-1. @ 11.014'; WOC X TACT. @ 7.929-7.759'; D. 5,260' - NOT FREE; PUP: CUT CSG. @ 3,280'-NCSQZ. HOLES @ 1.460'; ACT. @ 759'; WOC X TAG CIT. @ 559'; WOC X TAG CIT. @ 559'; WOC X TAG CIT. Electronic Submission #For CIMAREX EN Inmitted to AFMSS for process EYLER  Submission)  THIS SPACE FOR	give subsurface locations the Bond No. on file with sults in a multiple completed only after all requirements of the Bond No. on file with sults in a multiple completed only after all requirements of the Bond No. on file with sults in a multiple complete only after all requirements of the Bond No. on	and measured and BLM/BIA. Requision or recompletients, including recom	d true vertical de uired subsequent on in a new interchamation, have be 100'; PRES. TE 100'; PRE	pths of all pertin reports must be reval, a Form 316 peen completed a RECLAM  BLM: WOC: 60#XHOLD; 1P-TO.750# CMI. @  LL BELOW GRECL.  DUE: 10 CEPTED 02300E)  WAY  UREAU OF LA	ATTON PROCE ATTACHED  SROUND AMATIC  FOR RECU	DURE

# Additional data for EC transaction #463296 that would not fit on the form

32. Additional remarks, continued

LEVEL DRY HOLE MARKER. WELL PLUGGED AND ABANDONED 04/26/19.



## United States Department of the Interior

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

### Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1 The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver
Environmental Protection Specialist
575-234-5943

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Evnironmental Protection Specialist 575-234-5996

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612