Office	State of New Mexico	Form C-103
<u>District !</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO.
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-04914 5. Indicate Type of Lease
District III - (505) 334-6178	1220 South St. Francis Dr.	STATE STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,	o. State Off & Gas Ecase No.
87505		<u> </u>
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  PROPOSALS.)		7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT
	Gas Well Other - Injection	8. Well Number 121 WIW
2. Name of Operator		9. OGRID Number
XTO ENERGY, INC.		005380
3. Address of Operator		10. Pool name or Wildcat
6401 HOLIDAY HILL RD, BLDG 5, MIDLAND TX 79707		ARROWHEAD GRAYBURG
4. Well Location		
Unit Letter A: 660 feet from the NORTH line and 660 feet from the EAST line		
Section 35	Township 21S Range 36	
Section	11. Elevation (Show whether DR, RKB, RT, GR, et	
	The Station (only months Digitally, 111, Oil, of	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ _ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON		RILLING OPNS.□ P AND A 🛛
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	<del>_</del>
DOWNHOLE COMMINGLE	_	_
CLOSED-LOOP SYSTEM		
OTHER:	☐ OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion		
XTO respectfully approval conduct to plug and abandon operations on the referenced well as follows.  1. SET A CIBP @3,700'. SPOT 30 SX OF CMT FROM 3,700'; C;rc MLF  2. TAG TOC @3,400'. PRESSURE TEST CSG (500 psi);  3. PERF @2,922' (2 SPF; 50' BELOW SEVEN RIVERS);  4. SPOT 22 SX OF CMT PLUG FROM 2,700 TO 2,923'; TAG TOC @2,700'.  5. PERF @339' (50' BELOW CSG SHOE);  6. 80 SX OF CMT CIRC TO SURF. CMT PLUG FROM 340' TO SURF. TAG TOC @SURF.  Cut off well head 3' below CL in STACL 4" Above ground micro M		
XTO respectfully approval conduct to plug and abandon operations on the referenced well as follows.		
1. SET A CIBP @3,700'. SPOT 30 SX OF CMT FROM 3,700'; C;r < ALF		
2. TAG TOC @3,400'. PRESSURE TEST CSG (500 psi);		
3. PERF @2,922' (2 SPF; 50' BELOW SEVEN RIVERS);		
4. SPOT <del>22.</del> SX OF CMT PLUG FROM 2,700 TO 2,923'; TAG TOC @2,700'.		
5. PERF @339' (50' BELOW CSG SHOE);		
6. 80 SX OF CMT CIRC TO SURF. CMT PLUG FROM 340' TO SURF. TAG TOC @SURF.		
CUT OFF WOLLHEAD 3' LOLOV. CI : WETALL WILL W' A		
[ CC. 07. 480.11.	in 3 become ce instance 9	dia 4 Above ground 2
-		m KR 🕏
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
	า	
SIGNATURE Church Couch TITLE Regulatory Coordinator DATE		
SIGNATURE Church Cover TITLE Regulatory Coordinator 6/14/19 DATE		
Type or print name Chery Rowell	E-mail address: cheryl_rowell	@xtoenergy.com
i ype or print name	E-mail address:	ONE:
For State Use Uniy		
APPROVED BY: X	TITLE Carling A	10. A DATE 1-18-19
APPROVED BY: Xens fat TITLE Congliance Office A DATE 6-18-19 Conditions of Approval (if app):		
thbio.m. (1, m.Q.).	•	


Conditions of Assertations

## ARROWHEAD GRAYBURG UNIT 121 WIW API 30-025-04914

## CLASS I WELL W/CLASS II OVERIDE DURING CMT STAGE

- 1. SET A CIBP @3,700'. SPOT 30 SX OF CMT FROM 3,700';
- 2. TAG TOC @3,400'. PRESSURE TEST CSG (500 psi);
- 3. PERF @2,922' (2 SPF; 50' BELOW SEVEN RIVERS);
- 4. SPOT 22 SX OF CMT PLUG FROM 2,700 TO 2,923'; TAG TOC @2,700'.
- 5. PERF @339' (50' BELOW CSG SHOE);
- 6. 80 SX OF CMT CIRC TO SURF. CMT PLUG FROM 340' TO SURF. TAG TOC @SURF.

## THIS PROCEDURE IS PENDING C-103 APPROVAL FROM NMOCD/BLM. DEPTHS & VOLUMES MAY BE SUBJECT TO CHANGE.



## **GENERAL CONDITIONS OF APPROVAL:**

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.