

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised August 1, 2011

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

**HOBBBS, OCD**  
 JUN 13 2019  
**RECEIVED**

WELL API NO. 30-015-00960
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Artesia Metex Unit
8. Well Number 052
9. OGRID Number 269864
10. Pool name or Wildcat Artesia QU-GB-SA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other

2. Name of Operator  
State of New Mexico for Canyon E&P Company

3. Address of Operator  
1625 N. French Drive Hobbs, NM 88249

4. Well Location  
 Unit Letter M : 660 feet from the South line and 660 feet from the West line  
 Section 25 Township 18S Range 27E NMPM Eddy County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/> XX <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	<i>PNR</i>
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**SEE ATTACHED**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_  
**For State Use Only**

APPROVED BY: Kerry Forte TITLE Compliance Officer A DATE 6-14-19  
 Conditions of Approval (if any): \_\_\_\_\_

Plugging Report  
Artesia Metex Unit  
API 30-015-00960

5/29/2019 Cleared location with backhoe and tested anchors. Moved rig to location and dug out surface head.

5/30/2019 Rigged up and nipped down wellhead. Installed BOP and worked packer free. Packer started swabbing fluid up the casing. Moved in vac truck to catch fluid. POOH with 59 jts of 2 3/8" IPC tubing. Set 4 1/2" CIBP at 1773'. RIH with tubing and tagged CIBP. Circulated MLF and tested casing to 500#. Casing good. Spot 35 sx cement on top of CIBP. POOH and SION.

5/31/2019 Perforated 4 1/2" casing at 465'. Established circulation and pumped cement down the 4 1/2" casing to the perms at 465' and up the annulus to surface. Took 135 sx cement to get cement to the pit. Rigged down. Cement had fallen from surface. WOC. Dug out wellhead and cut off. Filled the 4 1/2" and 8 5/8" casing to surface with 30 sx cement. Installed marker, cut off anchors, cleaned the pit and cleared location.