B	UNITED STATE PARTMENT OF THE I UREAU OF LAND MANA	NTERIOR		B NO. 1004-0137 es: January 31, 2018	
SUNDRY	NOTICES AND REPO	RTS ON WELLS	UUUS ( 5. Lease Serial No NMNM1342		
Do not use thi abandoned wei	is form for proposals to II. Use form 3160-3 (AP	D drill or to re-enter an D) for such proposals.	6. If Indian, Allot	tee or Tribe Name	
SUBMIT IN 1	TRIPLICATE - Other ins	tructions on page 2	7. If Unit or CA//	Agreement, Name and/or No	
. Type of Well D Oil Well S Gas Well D Oth		60 ° °	8. Well Name and DOROTHY M		
Name of Operator MARATHON OIL PERMIAN L	Contact: LC E-Mail: mszudera	MELISSA SZUCEA	9. API Well No. 30-025-2522	20	
a. Address 5555 SAN FELIPE ST HOUSTON, TX 77056		3b. Phone No. (include area code Ph: 713-296-3179		ol or Exploratory Area RROW (GAS)	
Location of Well (Footage, Sec., T	., R., M., or Survey Description	n)	11. County or Par	11. County or Parish, State	
Sec 9 T19S R32E Mer NMP N	NWSE 1650FSL 1650FE	L	LEA COUN	LEA COUNTY, NM	
12. CHECK THE A	PROPRIATE BOX(ES)	) TO INDICATE NATURE O	F NOTICE, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION		TYPE OF	ACTION		
Notice of Intent	☐ Acidize	Deepen	Production (Start/Resume	e) 🔲 Water Shut-Of	
	Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Final Abandonment Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	Plug and Abandon	Temporarily Abandon Water Disposal		
. Describe Proposed or Completed Op		ent details, including estimated startin , give subsurface locations and measu			
following completion of the involved testing has been completed. Final Al determined that the site is ready for f	l operations. If the operation re bandonment Notices must be find inal inspection.	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ	<ul> <li>Required subsequent reports mu ompletion in a new interval, a Form ling reclamation, have been completed</li> </ul>	st be filed within 30 days a 3160-4 must be filed once eted and the operator has	
following completion of the involved testing has been completed. Final Al	and on perations. If the operation re- bandonment Notices must be final inspection. sx cement. 1245p-1 025 C (B) Add 130 (B) Add tag. 400 5	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2114 Add flag 1 - Alug SEZS - Sy	<ul> <li>Required subsequent reports mu ompletion in a new interval, a Form ling reclamation, have been completed</li> </ul>	ist be filed within 30 days 1 3160-4 must be filed once eted and the operator has Trans	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/352 2) 25sx @ 10450' - 10350'. J 3) 25sx @ 7300' - 7290'. 7 4) 50sx @ 4145' - 4045' P.S. 1 5) 40sx @ 2847' - 2747' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs.	A operations. If the operation re bandonment Notices must be final inspection. SX cement. 12450-1 025 (BS) 444 130 (BS) 444	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2114 Add flag 1 - Alug SEZS - Sy	<ul> <li>Required subsequent reports mu ompletion in a new interval, a Form ling reclamation, have been completed</li> </ul>	ist be filed within 30 days n 3160-4 must be filed once eted and the operator has Trans	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/35 2) 25sx @ 10450' - <del>1035</del> 0'. <b>1</b> 3) 25sx @ 7300' - <del>7200'</del> . <b>7</b> 4) 50sx @ 4145' - <del>4045</del> ' P.S. 1 5) 40sx @ 2847' - <del>2747</del> ' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens	d operations. If the operation re bandonment Notices must be fi inal inspection. sx cement. 124501 025 (BS) 444 tag. 400 5 2727 S. Verify cement @ surface ed facility.	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2114, Add flag 1 - Alug SGZS - Sq ce.	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498-11288 75- (Del.) SEE ASACLE CONSTINCTS	st be filed within 30 days a 3160-4 must be filed once eted and the operator has	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/35 2) 25sx @ 10450' - 10350'. J 3) 25sx @ 7300' - 7200'. 7 4) 50sx @ 4145' - 4045' P.S. f 5) 40sx @ 2847' - 2747' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens	A contraction of the operation re- bandonment Notices must be final inspection. Sx cement. 124501 025 (BS) Add 130 (BS) Add	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2114, Add flug 1 - Alug SEZS - Sy ce.	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498-11288 75- (Del.) SEE ASACHE CONSTINSTS CONSTINSTS	ist be filed within 30 days 1 3160-4 must be filed once eted and the operator has Trans	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/35 2) 25sx @ 10450' - 10350'. J 3) 25sx @ 7300' - 7200'. 7 4) 50sx @ 4145' - 4045' P.S. f 5) 40sx @ 2847' - 2747' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens	ed facility. Lectronic Submission a Strue and correct. Electronic Submission a For MARATH	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2114, Add floor 1 - Alug SEZS - Sy ce.	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498 - 11388 T 5 - (Del.) SEE ASACT CONSTILSTS CONSTILSTS II Information System the Hobbs	ist be filed within 30 days 1 3160-4 must be filed once eted and the operator has Trans	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/35 2) 25sx @ 10450' - 10350'. J 3) 25sx @ 7300' - 7200'. 7 4) 50sx @ 4145' - 4045' P.S. f 5) 40sx @ 2847' - 2747' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens	ed facility. Lectronic Submission f Electronic Submission f Electronic Submission f For MARATH Committed to AFMSS for Committed to AFMSS for Co	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2114, Add flog 1 - Alug SEZS - Sy ce.	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498 - 11388 T 5 - (Del.) SEE ASACT CONSTILSTS CONSTILSTS II Information System the Hobbs	ist be filed within 30 days n 3160-4 must be filed once eted and the operator has Transform APPROVAL	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/352 2) 25sx @ 10450' - 10350'. 1 3) 25sx @ 7300' - 7200'. 7 4) 50sx @ 4145' - 4045' P.S. 1 5) 40sx @ 2847' - 2747' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens <u>Selew 9 ream</u> 4. I hereby certify that the foregoing is	a operations. If the operation re bandonment Notices must be final inspection. Sx cement. 1245p 1 025 (B) Add 130 (B) A	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2114, Add flog 1 - Alug SEZS - Sy ce.	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498-11388 TS- (Del.) SEE ASACK CONSTINCT SEE ASACK CONSTINCT I Information System the Hobbs REZ on 06/13/2019 () ATORY COMPLIANCE REI	ist be filed within 30 days n 3160-4 must be filed once eted and the operator has Transform APPROVAL	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/35 2) 25sx @ 10450' - <del>10350'</del> . J 3) 25sx @ 7300' - <del>7200'</del> . <b>7</b> 4) 50sx @ 4145' - <del>4045</del> ' P.S. 1 5) 40sx @ 2847' - <del>2747</del> ' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens <b>Selew 9?Gen</b> 4. I hereby certify that the foregoing is Name( <i>Printed/Typed</i> ) MELISSA	l operations. If the operation re bandonment Notices must be fi inal inspection. sx cement. 124501 025 (BS) Add tag. 400 5 2727 S. Verify cement @ surfa ed facility. d (exc) dc s true and correct. Electronic Submission f For MARATH Committed to AFMSS for SZUDERA Submission)	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2114 Add floor 1 - Alug SEZS - Sq ce. 4468900 verified by the BLM Wel ION OIL PERMAN LLC, sent to or processing by PRISCILLA PE Title REGUL	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498 - 11788 SEE ACAL SEE ACAL CONSTINUES SEE ACAL CONSTINUES I Information System the Hobbs REZ on 06/13/2019 () ATORY COMPLIANCE REI 019	ist be filed within 30 days n 3160-4 must be filed once eted and the operator has Transform APPROVAL	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/35 2) 25sx @ 10450' - <del>10350'</del> . J 3) 25sx @ 7300' - <del>7200'</del> . <b>7</b> 4) 50sx @ 4145' - <del>4045</del> ' P.S. 1 5) 40sx @ 2847' - <del>2747</del> ' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens <b>Selew 9?Gen</b> 4. I hereby certify that the foregoing is Name( <i>Printed/Typed</i> ) MELISSA	l operations. If the operation re bandonment Notices must be fi inal inspection. sx cement. 124501 025 (BS) Add tag. 400 5 2727 S. Verify cement @ surfa ed facility. d (exc) dc s true and correct. Electronic Submission f For MARATH Committed to AFMSS for SZUDERA Submission)	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2114, Add flog 1 - Alug SEZS - Sq ce.	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498 - 11788 SEE ACAL SEE ACAL CONSTINUES SEE ACAL CONSTINUES I Information System the Hobbs REZ on 06/13/2019 () ATORY COMPLIANCE REI 019	ist be filed within 30 days n 3160-4 must be filed once eted and the operator has Trans DFR OFAPPROVAL	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/352 2) 25sx @ 10450' - 10350'. J 3) 25sx @ 7300' - 7200'. 7/ 4) 50sx @ 4145' - 4045' P.S. f 5) 40sx @ 2847' - 2747' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens <b>Sel and Printed</b> (Electronic S Name (Printed/Typed) MELISSA Signature (Electronic S Approved By nditions of approval, <i>ft</i> any, are attache tify that the applicant holds legal or equilibrium of approval, ft any, are attaches	a operations. If the operation re bandonment Notices must be fi inal inspection. SX cement. 124501 025 (B) Add 130 (B)	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2 114 Add floor 1 Alug SEZS - S y ce. Ce. Ce. Ce. Ce. Ce. Ce. Ce.	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498 - 11788 SEE ACAL SEE ACAL CONSTINUES SEE ACAL CONSTINUES I Information System the Hobbs REZ on 06/13/2019 () ATORY COMPLIANCE REI 019	st be filed within 30 days n 3160-4 must be filed once eted and the operator has Trann D FOR APPROVAL	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/352 2) 25sx @ 10450' - 10350'. J 3) 25sx @ 7300' - 7200'. 7 4) 50sx @ 4145' - 4045' P.S. f 5) 40sx @ 2847' - 2747' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens <b>Belen 9 (Complete</b> 4. I hereby certify that the foregoing is Name (Printed/Typed) MELISSA Signature (Electronic S	a operations. If the operation rebandonment Notices must be final inspection. Sx cement. 124501 02500000000000000000000000000000000000	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2 114 Add flog 1 Alug SEZS - Sq ce. Ce. Ce. Ce. Ce. Ce. Ce. Ce.	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498-11388 SEE ASACK CONSTINST SEE ASACK CONSTINST CONSTINST CONSTINST CONSTINUE CONSTINU	st be filed within 30 days n 3160-4 must be filed once eted and the operator has Trann DER P CAPPROVAL	
following completion of the involved testing has been completed. Final Al determined that the site is ready for f 1) 4-1/2 CIBP @ 12450' w/352 2) 25sx @ 10450' - 10350. 1 3) 25sx @ 7300' - 7200'. 7 4) 50sx @ 4145' - 4045' P.S. 1 5) 40sx @ 2847' - 2747' P.S. 6) 40sx @ 1166' - 1066' P.S. 7) 125sx @ 435' - Surface P.S Install DHM. P&A mud between all plugs. Closed loop all fluids to licens <b>Sellen 9 (Gene</b> 4. I hereby certify that the foregoing is Name ( <i>Printed/Typed</i> ) MELISSA Signature (Electronic S Approved By Inditions of approval, if any, are attached tify that the applicant holds legal or equic the world entitle the applicant to condi- tie 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	a operations. If the operation re bandonment Notices must be final inspection. Sx cement. 12450 1 035 (BS) Add 130 (BS) Add	e the Bond No. on file with BLM/BIA esults in a multiple completion or reco iled only after all requirements, includ 2 114 Add flog 1 Alug SEZS - Sq ce. Ce. Ce. Ce. Ce. Ce. Ce. Ce.	A. Required subsequent reports mu impletion in a new interval, a Form ling reclamation, have been completing 1498 - 11798 SEE ACACKE CONSTINUES SEE ACACKE CONSTINUES CONSTINUES II Information System the Hobbs REZ on 06/13/2019 () ATORY COMPLIANCE REI 019 OFFICE USE	st be filed within 30 days n 3160-4 must be filed once eted and the operator has Trans DFR P C-15-1 Date ent or agency of the United	

Additional data for EC transaction #468900 that would not fit on the form

32. Additional remarks, continued

• .

.

## MAVERICK WELL PLUGGERS

COMPANY: MARATHON OIL PERMIAN WELL NAME: Drothy MCKAY FEd. WELL #: / COUNTY: LEA, N. Mex. LEASE ID: SW1077

SURFACE CASING								
OD	WT/FT	GRADE	SETAT	TOC				
133	72	I-35	385	Surfi				
INTERMEDIATE CASING								
OD	WT/FT	GRADE	SETAT	TOC				
858	32	5-55	4095	2520				
PRODUCTION CASING								
OD	WT/FT	GRADE	SETAT	1'OC				
42	135	P-110	12,983	2520				
TUBING								
OD	WT/FT	GRADE	SET AT	I TAC				
	1							



Marath	onOil <sup>w</sup>	Wellbore Schematic Well Name: DOROTHY MCKAY FED 1 30-025-25220				
State/Province NEW MEXICO	Country UNITED STATES	Latitude (*) 32.67208810	Longitude (*) - 103,7675805	North/South Distance (f	I) North/South Reference	
APV IPO UM 3002525220	RECEDENT STATE AND THE REPORT FOR	Ground Elevation (f	t) Drilling Rig Spud D 1/13/1976	Date Well Original Completion	n Date Well First Production Date 5/10/2012	
002525220	horate a subscript Address.			<u>_</u>	15/10/2012	
	DOI	ROTHY MCKAY FED 1,	6/6/2019 10:17:11 AN	l		
MD (ftKB)		Vertica	I schematic (actual)			
0.0						
17.1	na komponenska komponenska u Bogor Benna (V Rei Dag Benna Dagor Bogor Bogor)				5; 72.00; J55; 17.0-385.0	
384.8				Casing Joints; 8.625 / 4,095.0		
2,520.0				/ 1/13/1976 / 1-1; Tubing; 2.875; 2		
4,095.1		·····		12,983.0 Production Casing C		
12,553.1	12,553.0-12,557.0; TCP, Si Calculated She	ot Total: 1	84	12,983.0; 1/13/1976		
12,557.1	Link	Phasing: ed Zone:				
12,571.8	12,572.0-12,574.0; TCP; Si Calculated Sho					
12,574.1	Link	ed Zone:				
12,596.1						
12,607.9	12,608.0-12,614.0; TCP: Si Celculated Sho		88 0%0 88 98 84 98			
12,613.8	Lint	ed Zone:				
12,625.0	12,625.0-12,628.0; TCP; SI Calculated Sho		X4 X035 S2 2657			
12,628.0	Link	ed Zonë: 😽				
12,653.9	12,654.0-12,663.0; TCP; SI Calculated Sho		85			
12,663.1	Link	ed Zone <sup>.</sup> 😽		Cement Sqbeeze; 12 1/13/1976	2,608.0-12.851.0;	
12,806.1		ot Total: 1	44 47 47 47 47			
12,809.1	Link	ed Zone:				
12,848.1	12,848.0-12,851.0; TCP; SI Calculated Sho		86 - 766 82 - 767 84 - 778			
12,851.0	Link	ed Zone:				
12,982.9						
www.marathong	all com	Page	1/1		Report Printed: 6/6/20	

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses.** Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u> From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted

١